BUREAU VERITAS

BV No. 09426

LIFTING EQUIPMENT INSPECTION REPORT	Area: DAMMAM	Inspection Date: APRIL 04.2021	Inspection Time: —	Previous Sticker No.: 20-9-910 Issued By: BV
Department / Contractor: SUPTASR	Equipment Number: S20AG-176	Equipment Location: DMM YARD	Inspection Result: ☑ Pass ☐ Fail	New Sticker No.: BV-21-00
Manufacturer: GENIE	Model: Z-62/40	Capacity: 227KG / Type: Manlift	Equipment Serial Number: Z620-311	Sticker Expiration Date: OCT 03, 2021

Above Equipment Was inspected by **Bureau Veritas** in accordance with applicable Saudi Aramco GI's ASME and API standards. Deficiencies that require corrective action are listed below. Specific repairs to correct each deficiency should be noted in the corrective action taken column

No.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
1	Periodic inspection and function test for	
	Boom supported elevating work platform	
	As per as Saudi Aramco GI7-020, ANSI 92.5.	
	"PASS"	

RECEIVER NAME: Mahtab Ishan SIGNATUE: A.Khan INSPECTOR NAME: 18-009

BADGE#: 2470523982 TELEPHONE No.: 0581849646 TELEPHONE No.: M. AMJAD

When re-inspection is requested, a complete copy of this report should be ready review by the inspector.

Distribution: Original-Proponent, 1st Copy -2nd Copy - Inspector Agency