BUREAU VERITAS

BV No. 0105204

LIFTING EQUIPMENT INSPECTION REPORT	Area: DAMMAM	Inspection Date: SEP 03, 2022	Inspection Time: 9:00	Previous Sticker No. 215-024011 Issued By CIMS
Department / Contractor: SUDAIR	Equipment Number: S20AG-176	Equipment Location: DMM/ORD	Equipment Result: ☑ Pass ☐ Fail	New Sticker No.: BV-21-5617
Manufacturer: GENIE	Model: Z 60/40	Capacity: 227KG / Type: MEWP	Equipment Serial Number: Z62D-311	Sticker Expiration Date: MAR-02-2023

Above Equipment was inspected by Bureaeu Veritas in accordance with applicable Saudi Aramco GI's ASME and API Standards. Deficiencies that require corrective actions are listed below. Specific repairs to correct each deficiency should be noted in the corrective action taken column.

No.	DEFECIENCIES	CORRECTIVE ACTION TAKEN
*	Periodic Inspection and Function test for	
	Boom supported Elevating work platform	
	As per ASSAMCO GI 7.030, ANSI 92.5	
	"PASS"	

RECEIVER NAME: THASEER SIGNATURE: INSPECTOR NAME: M. OMARS

BADGE#: 9031 TELEPHONE No.: 055 272 8031 TELEPHONE No.: 78-009

When re-inspection requested, a complete copy of this report should be ready review by the inspector.

Distribution: Original-Proponent, 1st Copy-2nd Copy - Inspector Agency