Report of Thorough Examination of Boom Supported Elevating Work Platform (Manlift)

Report No:	TEST-297-34642-13	**Report Issue Date:**	15 June 2025
Work Order No:	34642	**Inspection Type:**	Initial Visual & Functional
Customer Name:	Sudhir Equipment Rental Co.		
Work Location:	Dammam	**Equipment Type:**	Boom Supported Elevating Work Platform (Manlift)
Standard Reference:	ANSI A92.5	**Manufacturer:**	Zhejiang Dingli Machinery Co. Ltd.-2024
Inspection Date:	15 June 2025	**Equipment Model:**	BA20CRT2
Next Inspection Date:	14 December 2025	**Sticker No:**	62115
Measuring & Testing Equipment used:	Level Measuring (MLI-001) , Measuring Tape (TEST-MT8M-014)		

Serial No.	Description	SWL	Reason For Examination	Result	Safe To Use
BARC024I00536	Diesel-Powered Boom-Supported Elevating Work Platform Owner Tracking No.: S20AD-1783 Rated Load: 300 kg (2 Persons +140 kg Equip.) Power: 18.2 kW Max. Working Height: 20.15m Max Wind Speed: 12.5 m/s Max. Manual Force: 400N Max. Work Pressure: 240 bar Gross Weight: 8450 kg Year of Manufacturing: 2024 Location: Sudhir's yard, Dammam	300 kg	B	Accepted	Yes

Reason For Exam.	A- 3 Months	B- 6 Months	C- 12 Months	D- Written Scheme	E- Exceptional Circumstance	F- Installation

Result	ACCEPTED	REJECTED (See Attached Defect Report)

I hereby declare that the above information is correct and that the equipment has been thoroughly examined as far as possible in accordance with the appropriate provisions and that at the time of the examination is found to be free from any defect likely to affect safety.

TEST Approved Examiner:	Abdulaziz Mater AlShammari	**Approved By:**	Mostafa Sharshar
Signature		**Designation:**	Lifting Technical supervisor
		Signature:	

No liability will be considered against TEST company for failure, damage or other occurrence to Client owned or operated equipment due to misuse, improper installations, poor maintenance, weather/environmental conditions & equipment operator/user mistakes or uncontrolled operation & maintenance.

This Inspection Certificate/Report shall not be reproduced except in full without the approval of TEST Company and the Client.

شركة الفنيين المتخصصين لفحص المعدات
س.ت ٢٠٥٠٠٨٦٥٥١
المملكة العربية السعودية
TEST
C.R. 2050086551
Testing Equipment Specialist Team Co.

QC
TEST
REVIEWED BY:

Testing Equipment Specialist Team Co.
C.R. Number: 2050086551
Tel: +966 13 808 4277
Email: sales@testcosa.com

Boom Supported Elevating Work Platform (Manlift) Inspection Checklist

Customer Name:	Sudhir Equipment Rental Co.		
Report No:	TEST-297-34642-13	**Report Issue Date:**	15 June 2025
Work Order No:	34642	**Work Location:**	Dammam
Standard Reference:	ANSI A92.5	**Equipment Type:**	Boom Supported Elevating Work Platform (Manlift)
Inspection Date:	15 June 2025	**Equipment Serial No.:**	BARC024I00536

ID	Item	Pass	Fail	N/A	Comments
1	Equipment documentation is available	✓			
2	Equipment operated by qualified person	✓			
3	Serial No. , SWL, Manf. Name are clearly marked	✓			
4	Maximum number of persons is clearly marked	✓			
5	Maximum platform reach and height are clearly marked	✓			
6	Maximum travel height is clearly marked	✓			
7	AC or DC power rated is clearly marked			✓	
8	Direction arrows are clearly marked	✓			
9	Travelling , raising and lowering alarms are working properly	✓			
10	Tires and thread are not damaged and it’s in a good condition	✓			
11	Outriggers and stabilizer are free of oil leakage			✓	
12	Outriggers are free of nicks, gouges or cracks			✓	
13	Outriggers pad are in good condition			✓	
14	No evidence of oil leakage under equipment	✓			
15	Equipment is free from corroded or defective members	✓			
16	No loose nuts, bolts are missing or worn	✓			
17	Battery is secured and in good condition	✓			
18	Oil and water level	✓			
19	No major leakage at engine	✓			
20	Swing ring mounted blots are lubricated and fully secured	✓			
21	Ground controls are clearly marked for direction and mode of operation	✓			
22	Ground controls return to off position when released	✓			
23	Ground control is provided with emergency stop button	✓			
24	Ground control is provided with emergency lowering , rotating and retracting	✓			
25	Over-ride function is provided at ground control	✓			
26	Ground controls are protected against inadvertent operation	✓			
27	All gauges at ground control are in good condition	✓			
28	All ground control are working in a satisfactory manner	✓			
29	Ground control is protected against inadvertent movement	✓			
30	Boom main lifting cylinder is free oil leakage	✓			
31	Boom main lifting cylinder is free of nicks, gouges or cracks	✓			

32	Boom main lifting cylinder oil seal is not damaged	✓			
33	All hydraulic hoses are free of cracks or oil leakage	✓			
34	All hydraulic hoses fittings are fully secured and not leaking	✓			
35	Boom sections are not damaged and free of deformation	✓			
36	All electrical cable and wiring are not damaged and fully secured	✓			
37	Platform main structure is free from deformation, corroded or bended members	✓			
38	Platform surface is skid-resistant with at least 18 inches width	✓			
39	Platform is provided with guardrail with 42 inches height -/+ 3 inches	✓			
40	Platform is provided with at least 4 inches toeboard	✓			
41	Platform is provided with anchor point for body harness and it’s in a good condition	✓			
42	Platform gate opens inward or bar lock gate	✓			
43	Platform electrical wiring are not damaged and fully secured	✓			
44	Platform controls are clearly marked	✓			
45	Platform controls return to off position when released	✓			
46	Tilt alarm at 5 degree out of level is fitted and operable	✓			
47	Platform controls are protected against inadvertent operation	✓			
48	Safety devices	✓			
49	Operational and performance test	✓			
50	General condition	✓			