BUREAU VERITAS

BV No. 235710

LIFTING EQUIPMENT INSPECTION REPORT	Area: DAMMAM	Inspection Date: JUNE 22, 2023	Inspection Time: 9:00	Previous Sticker No. Initial Issued By
Department / contractor: SUDAIR	Equipment Number: S43AG-181	Equipment Location: DAMMAM	Equipment Result: ☑ Pass ☐ Fail	New Sticker No. BU-21-9697
Manufacturer: GENIE	Model: ZX-135/70	Capacity: 227KG / Type: MEWP	Equipment Serial Number: ZX135H-4129	Sticker Expiration Date: DEC 21, 2023

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI`s , ASME And API Standards. Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column.

No.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
*	Initial inspection and Function test for	
	Boom Supported Elevating Work Platform	
	As per As S.Aramco GI 7.03, ANSI 92.5	
	"Pass"	
*	COC was checked at time of inspection	

RECEIVER NAME: THAJEER SIGNATURE: INSPECTOR NAME: M. Osama

BADGE#: TELEPHONE NO.: TELEPHONE NO.: 18-009

When re-inspection requested, a Complete Copy of This Report Should Be Ready For Review By The Inspector.

Distribution: Original-Proponent, 1st Copy - second 2nd Copy - Inspector Agency