BUREAU VERITAS

BV No. 239205

LIFTING EQUIPMENT INSPECTION REPORT	Area: DAMMAM	Inspection Date: JAN 28, 2024	Inspection Time: 10:30	Previous Sticker No. Initial Issued By
Department / contractor: SUDAJR	Equipment Number: S43AG-181	Equipment Location: DMMYARD	Equipment Result: ☑ Pass ☐ Fail	New Sticker No.: BU-23-0864
Manufacturer: GENIE	Model: ZX-135/70	Capacity: 272KG / Type: MEWP	Equipment Serial Number: ZX135H-4129	Sticker Expiration Date: JULY 27, 2024

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI's , ASME And API Standards. Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column.

No.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
*	Initial Inspection and function test for	
	Boom Supported Elevating work plat form.	
	As per as SAPMO GI 7.03 & ANSI 92.5	
	Pass	

RECEIVER NAME: ARIF SIGNATURE: INSPECTOR NAME: Mehmet

BADGE#: TELEPHONE NO.: TELEPHONE NO.: 5019106

'hen re-inspection requested, a Complete Copy of This Report Should Be Ready For Review By The Inspector.

Distribution: Original-Proponent, 1st Copy - second 2nd Copy - Inspector Agency