BUREAU VERITAS

BV No. 0105362

LIFTING EQUIPMENT INSPECTION REPORT	Area: DAMMAM	Inspection Date: OCT 13, 2022	Inspection Time: 9:00	Previous Sticker No. Initial Issued By
Department / Contractor: S VDHIR	Equipment Number: S40SG-182	Equipment Location: DMM YARD	Equipment Result: ☑ Pass ☐ Fail	New Sticker No.: BV-21-5673
Manufacturer: GENIE	Model: SX-125XC	Capacity: 227KGO / Type: MEWP	Equipment Serial Number: SX125D-913	Sticker Expiration Date: APRIL 12, 2023

Above Equipment was inspected by Bureaeu Veritas in accordance with applicable Saudi Aramco GI's ASME and API Standards. Deficiencies that require corrective actions are listed below. Specific repairs to correct each deficiency should be noted in the corrective action taken column.

No.	DEFECIENCIES	CORRECTIVE ACTION TAKEN
*	Initial inspection and function test for	
	Boom supported elevating work platform	
	as per as S.ARMCO GI7.031 ANSI92.5	
	'PASS'	
*	manf test certificate was verified at time of inspection	

RECEIVER NAME: THAISEER SIGNATURE: INSPECTOR NAME: M. ...

BADGE#: 8031 TELEPHONE No.: 055222 8031 TELEPHONE No.: 18...

When re-inspection requested, a complete copy of this report should be ready review by the inspector.

Distribution: Original-Proponent, 1st Copy-2nd Copy - Inspector Agency