BUREAU VERITAS

BV No. 237165

LIFTING EQUIPMENT INSPECTION REPORT	Area: DAMMAM	Inspection Date: SEP28,2023	Inspection Time: 9:00	Previous Sticker No: 21-7759 Issued By: BV
Department / contractor: SUDAIR	Equipment Number: S40SG-182	Equipment Location: DAMMAM	Equipment Result: ☑ Pass ☐ Fail	New Sticker No.: BV-21-9574
Manufacturer: GENIE	Model: SX-125 XC	Capacity: 227KG / Type: MEMP	Equipment Serial Number: SX125D-913	Sticker Expiration Date: MARCH 27,2024

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI`s , ASME And API Standards. Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column.

No.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
1	Periodic Inspection and function test for	
	Boom Supported Elevating work platform	
	As per ASSAMCO GI 7.030 Annex 2.5	
	"Boss"	

RECEIVER NAME: ARIL SIGNATURE: INSPECTOR NAME: Mohammad

BADGE#: TELEPHONE NO.: TELEPHONE NO.: 800 19106

When re-inspection requested, a Complete Copy of This Report Should Be Ready For Review By The Inspector.

Distribution: Original-Proponent, 1st Copy - second 2nd Copy - Inspector Agency