THOROUGH EXAMINATION CERTIFICATE OF SCISSOR LIFT

Report No:	DAM-INS-2025-08-06246	**Report Issue Date:**	13-Aug-2025
Customer Name:	Sudhir Equipment Rental Co.	**Inspection Type:**	Visual Inspection
Address:	Dammam	**Serial Number**	JPAC024I04491
Site Location:	Dammam	**Equipment Id Number:**	SD10ESL-1939
Standard Reference:	ASME B30.23	**Manufacturer:**	Dingli
Inspection Date:	10-Aug-2025	**Equipment Model/Type:**	JCPT1008AC
Next Inspection Date:	09-Feb-2026	**Sticker No:**	DAM/004988

Description		Capacity/SWL	Reason For Examination	Result	Safe To Use
Working height	10 Meter		B	Satisfactory	YES
Basket	Satisfactory				
Manual Control	Satisfactory				
Operating Pressure	Satisfactory				
Electrical Control	Satisfactory				
Hydraulic System	Satisfactory				
Fire Extinguishers	Satisfactory				
General Condition	Satisfactory				

Reason For Exam.	A	B	C	D	E	F
	3 Months	6 Months	12 Months	Written Scheme	Exceptional Circumstance	Installation

Result	ACCEPTED	REJECTED (See Attached Defect Report)

Declaration:

I hereby declare that the above information is correct and that the equipment has been thoroughly examined as far as possible in accordance with the appropriate provisions/Standards that at the time of the Inspection/examination and found to be free from any defect likely to affect safety other than theses detailed above.

Inspected By:	UIC 40 INSPECTOR	**Approved By:** MOHAMED KANI S.	**Signature:**
Stamp By:		**Designation:** Inspection Supervisor	

No liability will be considered against **UNIVERSAL INSPECTION COMPANY** for failure, damage or other occurrence to Client owned or operated equipment due to misuse, improper installations, poor maintenance, weather/environmental conditions & equipment operator/user mistakes or uncontrolled operation & maintenance.
This Inspection Certificate/Report shall not be reproduced except in full without the approval **UIC** and the Client.

VENDOR ID: 10044577 | APPROVED VENDOR | VENDOR ID : 11052442 | VENDOR ID: 5014041 | VENDOR ID: 10857