THOROUGH EXAMINATION CERTIFICATE OF SCISSOR LIFT

Report No:	DAM-INS-2025-01-00276	**Report Issue Date:**	16-Jan-2025
Customer Name:	Sudhir Equipment Rental Co.	**Inspection Type:**	Visual Inspection
Address:		**Serial Number**	JPR0024I00576
Site Location:	Dammam Yard	**Equipment Id Number:**	SD18SL-1955
Standard Reference:	ASME B30.23	**Manufacturer:**	Dingli
Inspection Date:	16-Jan-2025	**Equipment Model/Type:**	JCPT1823RTL
Next Inspection Date:	15-Jul-2025	**Sticker No:**	DAM/000693

Description		Capacity/SWL	Reason For Examination	Result	Safe To Use
Working height	18 Meter	N/A	B	Satisfactory	YES
Basket	Satisfactory				
Manual Control	Satisfactory				
Operating Pressure	Satisfactory				
Electrical Control	Satisfactory				
Hydraulic System	Satisfactory				
Fire Extinguishers	Satisfactory				
General Condition	Satisfactory				

Reason For Exam.	A 3 Months	B 6 Months	C 12 Months	D Written Scheme	E Exceptional Circumstance	F Installation

Result	ACCEPTED	REJECTED (See Attached Defect Report)

Declaration:

I hereby declare that the above information is correct and that the equipment has been thoroughly examined as far as possible in accordance with the appropriate provisions/Standards that at the time of the Inspection/examination and found to be free from any defect likely to affect safety other than theses detailed above.

Inspected By:	UIC 40 INSPECTER	**Approved By:** JASIM KHAN	**Signature:**
Stamp By:		**Designation:** Inspection Supervisor	

No liability will be considered against **UNIVERSAL INSPECTION COMPANY** for failure, damage or other occurrence to Client owned or operated equipment due to misuse, improper installations, poor maintenance, weather/environmental conditions & equipment operator/user mistakes or uncontrolled operation & maintenance.
This Inspection Certificate/Report shall not be reproduced except in full without the approval **UIC** and the Client.

VENDOR ID: 10044577 | APPROVED VENDOR | VENDOR ID : 11052442 | VENDOR ID: 5014041 | VENDOR ID: 10857