BUREAU VERITAS

**BV No.** 07370

| LIFTING EQUIPMENT INSPECTION REPORT | Area: DAHRAN | Inspection Date: DEC 17, 2020 | Inspection Time: — | Previous Sticker: No. 10111 Issued By Zamil |
|---|---|---|---|---|
| Department / Contractor: SUDHJR | Equipment Number: S43SJP-198 | Equipment Location: DAHRAN | Inspection Result: ☑ Pass ☐ Fail | New Sticker No.: 20-10948 |
| Manufacturer: JLG | Model: 1350SJP | Capacity: 230KG / Type: Manlift | Equipment Serial Number: 0300236646 | Sticker Expiration Date: JUNE 18, 2021 |

Above Equipment Was inspected by **Bureau Veritas** in accordance with applicable Saudi Aramco GI's ASME and API standards. Deficiencies that require corrective action are listed below. Specific repairs to correct each deficiency should be noted in the corrective action taken column

| No. | DEFICIENCIES | CORRECTIVE ACTION TAKEN |
|---|---|---|
| | Periodic Inspection and Function test | |
| | for Boom Supported Elevating work platform. | |
| | As per ASME GI 7.0 30, ANSI 92.5 | |
| | 'PASS' | |

RECEIVER NAME: Abdul [signature] SIGNATUE: [signature] INSPECTOR NAME: Mohamed Omar

BADGE#: TELEPHONE No.: TELEPHONE No.:

When re-inspection is requested, a complete copy of this report should be ready review by the inspector.

**Distribution:** Original-Proponent, 1st Copy -2nd Copy - Inspector Agency