ESICO

شركة مساندة الإعمار للفحص
Emaar Support Inspection Co.
6888, King Faisal Bin Abdul Aziz St, Ad Danah, Ras Tannurah, Saudi Arabia 32817
Tel : +966 507259023, +966 136670779, 055 8889186, 050 0484444
Email : info@esico.com.sa Website : www.esico.com.sa C.R : 2054100036

CERTIFICATE OF THOROUGH EXAMINATION AND / OR TEST OF LIFTING APPLIANCE OR ACCESSORY

Date of thorough examination : 24-06-2025		Date of issue : 24-06-2025	Report No. : ESICO-LFT-R25-4339	
Name & Address of employer		Location	Sticker No	Standards
SUDHIR EQUIPMENT RENTALS COMAPNY		Riyadh	5991	SASO ISO EN 280
Equipment Identification No	Equipment Description	Safe Working Load(s)	Date of Manufacture	Manufacturer Name
S26SPJ-1990 OR C170004210	SPIDER LIFT TYPE: COMPACT CRAWLER ARTICULATED BOOM MODEL: X26JP Max.working height: 25.6M Max.wind speed:12.5m/s Max.manual force:400N Max.occupation person: 2	RATED LOAD : 230 KG	2024	JLG

Is this the first examination after installaton or assembly at a new site or location?	Yes	-	No	✗	Was the examination carried out within an interval of?	- 6 Months	
If the answer to the above question is YES, has the equipment been installed correctly?	Yes	-	No	-	In accordance with an examination scheme?	Yes ✓	No -
					After the occurence of exceptional circumstances?	Yes -	No ✗

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect (if none state NONE) : NONE	
Is the above an existing or imminent danger to persons, Note: This is a reportable defect?	N/A
Is the above a defect which is not yet could become a danger to persons (if YES state the date by when)	Yes by : N/A
Particulars of any repair, renewal or alteration required to remedy the defect identified above : N/A	
Particulars of any tests carried out as part of the examination (if none state NONE) : NONE	
Observation/additional comments relative to this thorough examination : Visual and functions checks conducted at the time of inspection machine was found satisfactory	

For confirmation scan QR code
search with report number : ESICO-LFT-R25-4339

QA/QC DEPARTMENT
EMAAR SUPPORT INSPECTION CO

Safe to operate

Next Inspection : 23-12-2025

Inspected by : Mohamed Askar Ali

EMAAR SUPPORT INSPECTION CO. INSPECTOR C.R.: 2054100036

LEEA Full Member | أرامكو السعودية saudi aramco 10056897 | EP-Q4634 | NEOM 1100004098 | National Water Company 33564 | 10739 | sabic 001052261 | الشركة السعودية للكهرباء Saudi Electricity Company 05022531 | IAF | IAS