BUREAU VERITAS

BV No. 0106920

LIFTING EQUIPMENT INSPECTION REPORT	Area: RASALKHAIR	Inspection Date: JUNE 02, 2022	Inspection Time: 8:45	Previous Sticker No. 21-3338 Issued By BU
Department / Contractor: SUDAIR	Equipment Number: S40SG-208	Equipment Location: MYDP	Equipment Result: ☑ Pass ☐ Fail	New Sticker No. BU-21-5028
Manufacturer: GENIE	Model: S125	Capacity: 227KG / Type: MEWP	Equipment Serial Number: S125120-363	Sticker Expiration Date: DEC 01, 2022

Above Equipment was inspected by Bureaeu Veritas in accordance with applicable Saudi Aramco GI's ASME and API Standards. Deficiencies that require corrective actions are listed below. Specific repairs to correct each deficiency should be noted in the corrective action taken column.

No.	DEFECIENCIES	CORRECTIVE ACTION TAKEN
*	Periodic inspection and function test for	
	Boom supported elevating work plat form	
	As per Saramco GI 70.30.AMT 92.5	
	'PASS'	

RECEIVER NAME: VBAYD ALLA SIGNATURE: [signature] INSPECTOR NAME: [signature]

BADGE#: TELEPHONE No.: TELEPHONE No.: 1 [illegible]

When re-inspection requested, a complete copy of this report should be ready review by the inspector.

Distribution: Original-Proponent, 1st Copy-2nd Copy - Inspector Agency