BUREAU VERITAS

BV No. 07378

LIFTING EQUIPMENT INSPECTION REPORT	Area: JUBAIL	Inspection Date: JAN 05, 2021	Inspection Time: —	Previous Sticker: No. 10120 Issued By Zamil
Department / Contractor: SUDHIR	Equipment Number: S405G-209	Equipment Location: JUBAIL	Inspection Result: ☑ Pass ☐ Fail	New Sticker No.: 20-10956
Manufacturer: GENIE	Model: S125	Capacity: 227KG / Type: Manlift	Equipment Serial Number: S125 12D-354	Sticker Expiration Date: JULY 04, 2021

Above Equipment Was inspected by **Bureau Veritas** in accordance with applicable Saudi Aramco GI's ASME and API standards. Deficiencies that require corrective action are listed below. Specific repairs to correct each deficiency should be noted in the corrective action taken column

No.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
	Periodic Inspection and Function test for	
	Boom Supported Elevating work Plat form	
	As per AS SARSMCO GI7.030, ANSI92.5	
	"Pass"	

RECEIVER NAME: Ali SIGNATUE: INSPECTOR NAME: 18-0007 M. Omar

BADGE#: TELEPHONE No.: TELEPHONE No.:

When re-inspection is requested, a complete copy of this report should be ready review by the inspector.

Distribution: Original-Proponent, 1st Copy -2nd Copy - Inspector Agency