ESICO

شركة مساندة الإعمار للفحص
Emaar Support Inspection Co.
6888, King Faisal Bin Abdul Aziz St, Ad Danah, Ras Tannurah, Saudi Arabia 32817
Tel : +966 507259023, +966 136670779, 055 8889186, 050 0484444
Email : info@esico.com.sa Website : www.esico.com.sa C.R : 2054100036

CERTIFICATE OF THOROUGH EXAMINATION OF MANLIFT

Date of thorough examination : 04-01-2026	Date of issue : 04-01-2026	Report No. : ESICO-LFT-R25-7081

Name & Address of employer	Location	Sticker	Standards
SUDHIR EQUIPMENT RENTALS COMAPNY	EXIT 15 SEVEN PROJECT	8733	SASO GSO EN 280, ANSI A92.5

Equipment Identification No	Equipment Description	Safe Working Load(s)	Date of Manufacture	Manufacturer Name
S48SJ-2165 OR 0300213727	MAN LIFT MODEL: 1500SJ MAX.PLAT FORM HEIGHT:150FT(45.72M) HORIZONTAL OUT REACH:80FT(24.38M) WORKING HEIGHT:156FT(47.72M) MAX.MANUAL FORCE:400N MAX.WIND SPEED:12.5M/S MAX.OCCUPATION PERSON: 2PEOPLE	RATED LOAD:227KG(2P)	2016	JLG

Is this the first examination after installaton or assembly at a new site or location?	Yes	-	No	✗	Was the examination carried out within an interval of?	-	6 Months
If the answer to the above question is YES, has the equipment been installed correctly?	Yes	-	No	-	In accordance with an examination scheme?	Yes ✓	No -
					After the occurence of exceptional circumstances?	Yes -	No ✗

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect (if none state NONE) : NONE	
Is the above an existing or imminent danger to persons, Note: This is a reportable defect?	No
Is the above a defect which is not yet could become a danger to persons (if YES state the date by when)	Yes by : N/A
Particulars of any repair, renewal or alteration required to remedy the defect identified above : NONE	
Particulars of any tests carried out as part of the examination (if none state NONE) : VISUAL INSPECTION AND FUNCTIONAL TEST.	
Observation/additional comments relative to this thorough examination : PLACE THE FIRE EXTINGUISHER AND MAINTENANCE THE DIGITAL METER.	

For confirmation scan QR code
search with report number : ESICO-LFT-R25-7081

QA/QC DEPARTMENT

Safe to operate

Next Inspection : 03-07-2026

Inspected by : Jay Prakash

INSPECTOR

LEEA Full Member | أرامكو السعودية saudi aramco 10056897 | EP-Q4634 | NEOM نيوم 1100004098 | شركة المياه الوطنية National Water Company 33564 | 10739 | سابك sabic 001052261 | الشركة السعودية للكهرباء Saudi Electricity Company 05022531 | IAF | IAS ACCREDITED