BUREAU VERITAS

BV No. 0105982

LIFTING EQUIPMENT INSPECTION REPORT	Area: HARADH	Inspection Date: JAN 15, 2023	Inspection Time: 9:00	Previous Sticker No. 15008 Issued By Zamil
Department / Contractor: SUDAIR	Equipment Number: S43 SJP-238	Equipment Location: H GCP-1	Equipment Result: ☑ Pass ☐ Fail	New Sticker No. BV-21-7342
Manufacturer: JLG	Model: 1350 SJP	Capacity: 500LBS / Type: MEWP	Equipment Serial Number: 0300267131	Sticker Expiration Date: JULY 14, 2023

Above Equipment was inspected by Bureaeu Veritas in accordance with applicable Saudi Aramco GI's ASME and API Standards. Deficiencies that require corrective actions are listed below. Specific repairs to correct each deficiency should be noted in the corrective action taken column.

No.	DEFECIENCIES	CORRECTIVE ACTION TAKEN
*	Periodic Inspection and function test for	
	Boom Supported Elevating work platform	
	As per ASSAMCO GI 7.030 and 592.5	
	"PASS"	

RECEIVER NAME: THAISAD SIGNATURE: INSPECTOR NAME: M. Ahmad

BADGE#: — TELEPHONE No.: TELEPHONE No.: 18-0029

When re-inspection requested, a complete copy of this report should be ready review by the inspector.

Distribution: Original-Proponent, 1st Copy-2nd Copy - Inspector Agency