C.R.NO. : 4030353203
C.C.J.NO. : 324468
TEL : +966 12 655 1888
FAX : +966 12 287 7770
ISO 9001:2015

HAYKALAH
INSPECTION & TRAINING
Values For Quality

هيكلة
الفحص والتدريب
قيم الجودة

س.ت. : ٤٠٣٠٣٥٣٢٠٣
غرفة تجاره : ٣٢٤٤٦٨
هاتف : ٩٦٦ ١٢ ٦٥٥ ١٨٨٨+
فاكس : ٩٦٦ ١٢ ٢٨٧ ٧٧٧٠+
ISO 9001:2015

THIRD PARTY INSPECTION CERTIFICATE

MANLIFT

Certificate No : HIT-CRT-22-1715 Job No JO-INS-22-907

Sticker No	1565
Result	Pass

Timesheet	CL-2610
Checklist	CL-2610

Client Name & Address		Inspection Date	13-Sep-2022
Sudhir Equipment Rental Company		Expiration Date	12-Mar-2023
Yanbu		Validity	6 Month's
Kingdom of Saudi Arabia		**Types of Inspection**	
Equipment Location	Yanbu	Periodic Visual & Functional	

Equipment Description	Load Test Chart			
Telescopic Boom Lift (Manlift) with single basket,	**Boom ↔**	**Radius →**	**Test Load**	**S.W.L.**
Double operative control system,	**(Meter)**	**(Meter)**	**(Tonne)**	**(Tonne)**
Diesel driven hydraulic.	NA	NA	NA	NA

Load Limit (S.W.L.)	230 kg	Manufacturer	JLG
Serial No.	0300256377	Date of Mfg.	2019
Model	1350 SJP	Owner ID/Plat No	S43SJP-239
Horizontal Outreach	24.38 m	Max Platform Height	41.15 m
Working Height	43.30 m	Machine Height	3.05 m
Wire Rope Dia	**Main: NA Aux: NA**	No. of Reeve	NA
Boom Length	NA	Machine Weight	20,400 Kg
Wheel Type	Tyre	Person Allowed	1

Previous Inspection Details	**Next Inspection Date**	Reference Standard
NA	13-Mar-23	ASME A 90.1

Recommendation

Found satisfactory at the time of Inspection.

Authorized By: ASHADULLAH KHAN

Inspected By: ISRAN SHAREEF

HAYKALAH 001

Signature & Stamp

No liabilities will be considered against Haykalah Inspection Est. for failure, damage or other occurrence to client owned or operated equipment due to misuse, improper installations, poor maintenance, weather/environmental conditions & equipment operator/user mistakes or uncontrolled operation & maintenance. The concerned inspector or representative has thoroughly examined the equipment in accordance to the relevant standards. Inspection indicates that the mentioned equipment/tools/machine has no apparent defects which may prove dangerous during normal operation and it's found satisfactory for further use with provided their regular maintenance and operated by a certified operator. This certificate/report shall not be generated without an official approval in between Haykalah Inspection Est. and Client. Certificate becomes invalid if any modification/repair is made to the equipment.

6988 ABU AL ABBAS IBN ABDULMUTALIB
ASH SHAHTI DISTRICT, JEDDAH 23513-2970
KINGDOM OF SAUDI ARABIA

EMAIL: hit@hakalah.com
WEB: www.haykalah-hit.com

٦٩٨٨ ابو العباس ابن عبدالمطالب
اشاتيى دستريك، جدة ٢٣٥١٣-٢٩٧٠
المملكة العربية السعودية