C.R.NO. : 4030353203
C.C.J.NO. : 324468
TEL : +966 12 655 1888
FAX : +966 12 287 7770
ISO 9001:2015

HAYKALAH
INSPECTION & TRAINING
Values For Quality

هيكلة
الفحص والتدريب
قيم الجودة

س.ت. : ٤٠٣٠٣٥٣٢٠٣
غرفة تجاره : ٣٢٤٤٦٨
هاتف : ٦٥٥ ١٨٨٨ ١٢ ٩٦٦+
فاكس : ٢٨٧ ٧٧٧٠ ١٢ ٩٦٦+
ISO 9001:2015

# THIRD PARTY INSPECTION CERTIFICATE
## MANLIFT

Certificate No : HIT-CRT-23-2550

Job No JO-INS-23-1404

| | |
|---|---|
| Sticker No | 2434 |
| Result | Pass |

| | |
|---|---|
| Timesheet | CL-4107 |
| Checklist | CL-4107 |

| Client Name & Address | | Inspection Date | 19-Mar-2023 |
|---|---|---|---|
| Sudhir Equipment Rental Company | | Expiration Date | 18-Sep-2023 |
| Jeddah | | Validity | 12 Month's |
| Kingdom of Saudi Arabia | | **Types of Inspection** | |
| Equipment Location | Asfan | Periodic Visual & Functional | |

| Equipment Description | Load Test Chart | | | |
|---|---|---|---|---|
| Manlift crane with single basket, | **Boom ↔** | **Radius →** | **Test Load** | **S.W.L.** |
| Double operative control system, | **(Meter)** | **(Meter)** | **(Tonne)** | **(Tonne)** |
| High performance to power ratio, | NA | NA | NA | NA |
| Diesel driven hydraulic. | | | | |
| | | | | |
| | | | | |

| | |
|---|---|
| **Load Limit (S.W.L.)** | 226.8 kg |
| Serial No. | 0300256377 |
| Model | 1350SJP |
| Max.Horiz Outreach | 24.38 m |
| Machine Height | 3.05 m |
| Wire Rope Dia | **Main: NA** **Aux: NA** |
| Boom Length | NA |
| Wheel Type | Tyre |

| | |
|---|---|
| Manufacturer | JLG |
| Date of Mfg. | 2019 |
| Owner ID/Plate No | S43SJP-239 |
| Max Platform Height | 41.15 m |
| Machine Weight | 20,411 kg |
| No. of Reeve | NA |
| Angle of Span | NA |
| Person Allowed | 2 |

| Previous Inspection Details | **Next Inspection Date** | Reference Standard |
|---|---|---|
| NA | 19-Sep-23 | ASME A 90.1 |

Recommendation

Found satisfactory at the time of Inspection.

**Authorized By: ASHADULLAH KHAN**

**Inspected By: KALEEM SHARIEF**

Kaleem Sharief

HAYKALAH 003

Signature & Stamp

**No liabilities will be considered against Haykalah Inspection Est. for failure, damage or other occurrence to client owned or operated equipment due to misuse, improper installations, poor maintenance, weather/environmental conditions & equipment operator/user mistakes or uncontrolled operation & maintenance. The concerned inspector or representative has thoroughly examined the equipment in accordance to the relevant standards. Inspection indicates that the mentioned equipment/tools/machine has no apparent defects which may prove dangerous during normal operation and it's found satisfactory for further use with provided their regular maintenance and operated by a certified operator. This certificate/report shall not be generated without an official approval in between Haykalah Inspection Est. and Client. Certificate becomes invalid if any modification/repair is made to the equipment.**

6988 ABU AL ABBAS IBN ABDULMUTALIB
ASH SHAHTI DISTRICT, JEDDAH 23513-2970
KINGDOM OF SAUDI ARABIA

EMAIL: hit@hakalah.com
WEB: www.haykalah-hit.com

٦٩٨٨ ابو العباس ابن عبدالمطالب
اشاتيى دستريك، جدة ٢٣٥١٣-٢٩٧٠
المملكة العربية السعودية