C.R.NO. : 4030353203
C.C.J.NO. : 324468
TEL : +966 12 655 1888
FAX : +966 12 287 7770
ISO 9001:2015

HAYKALAH INSPECTION & TRAINING
Values For Quality

هيكلة الفحص والتدريب
قيم الجودة

س.ت. : 4030353203
غرفة تجاره : 324468
هاتف : +966 12 655 1888
فاكس : +966 12 287 7770
ISO 9001:2015

THIRD PARTY INSPECTION CERTIFICATE
SCISSOR LIFT

Certificate No : HIT-CRT-23-2660

Job No JO-INS-23-1464

Sticker No	2097
Result	Pass

Timesheet	CL-3654
Checklist	CL-3654

Client Name & Address		Inspection Date	10-Apr-2023
Sudhir Equipment Rental Company		Expiration Date	9-Oct-2023
Duba		Validity	6 Month's
Kingdom of Saudi Arabia		**Types of Inspection**	
Equipment Location	Duba	Periodic Visual & Functional	

Equipment Description	Load Test Chart			
Scissor Lift with single basket,	**Boom ↔**	**Radius →**	**Test Load**	**S.W.L.**
Double operative control system,	**(Meter)**	**(Meter)**	**(Tonne)**	**(Tonne)**
Diesel driven hydraulic.	NA	NA	NA	NA

Load Limit (S.W.L.)	227 Kg
Serial No.	B200053043
Model	2632 ES
Horizontal Outreach	NA
Working Height	7.75 m
Wire Rope Dia	**Main: NA** **Aux: NA**
Boom Length	NA
Wheel Type	Tyre

Manufacturer	JLG
Date of Mfg.	2020
Owner ID/Plat No	SJ10ESL-243
Max Platform Height	11.5 m
Machine Height	3.05 m
Machine Weight	2118 kg
Angle of Span	NA
Person Allowed	1

Previous Inspection Details	**Next Inspection Date**	Reference Standard
NA	10-Oct-23	ASME A 90.1

Recommendation

Found satisfactory at the time of Inspection.

Authorized By: ASHADULLAH KHAN

Inspected By:RAGHIB SHAHAB KHAN

Signature & Stamp

No liabilities will be considered against Haykalah Inspection Est. for failure, damage or other occurrence to client owned or operated equipment due to misuse, improper installations, poor maintenance, weather/environmental conditions & equipment operator/user mistakes or uncontrolled operation & maintenance. The concerned inspector or representative has thoroughly examined the equipment in accordance to the relevant standards. Inspection indicates that the mentioned equipment/tools/machine has no apparent defects which may prove dangerous during normal operation and it's found satisfactory for further use with provided their regular maintenance and operated by a certified operator. This certificate/report shall not be generated without an official approval in between Haykalah Inspection Est. and Client. Certificate becomes invalid if any modification/repair is made to the equipment.

6988 ABU AL ABBAS IBN ABDULMUTALIB
ASH SHAHTI DISTRICT, JEDDAH 23513-2970
KINGDOM OF SAUDI ARABIA

EMAIL: hit@hakalah.com
WEB: www.haykalah-hit.com

6988 ابو العباس ابن عبدالمطالب
اشاتيى دستريك, جدة 23513-2970
المملكة العربية السعودية