ESICO

شركة مساندة الإعمار للفحص
Emaar Support Inspection Co.
6888, King Faisal Bin Abdul Aziz St, Ad Danah, Ras Tannurah, Saudi Arabia 32817
Tel : +966 507259023, +966 136670779, 055 8889186, 050 0484444
Email : info@esico.com.sa Website : www.esico.com.sa C.R : 2054100036

## CERTIFICATE OF THOROUGH EXAMINATION AND / OR TEST OF LIFTING APPLIANCE OR ACCESSORY

| | | | | |
|---|---|---|---|---|
| Date of thorough examination : 12-05-2025 | | Date of issue : 12-05-2025 | Report No. : ESICO-LFT-R25-4014 | |
| Name & Address of employer | | Location | Sticker No | Standards |
| SUDHIR EQUIPMENT RENTALS | | Riyadh | 5666 | SASO GSO EN 280 |
| Equipment Identification No | Equipment Description | Safe Working Load(s) | Date of Manufacture | Manufacturer Name |
| SJ10ESL-246 OR B200055386 | SCISSOR LIFT<br>MODEL:GS2632<br>Max. working height:9.80m<br>Max.number of occupatans: 2<br>Engine power: 24V | 227KG | 2020 | JLG |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Is this the first examination after installaton or assembly at a new site or location? | Yes | - | No | ✗ | Was the examination carried out within an interval of? | - 6 Months | |
| If the answer to the above question is YES, has the equipment been installed correctly? | Yes | - | No | - | In accordance with an examination scheme? | Yes ✓ | No - |
| | | | | | After the occurence of exceptional circumstances? | Yes - | No ✗ |

| | |
|---|---|
| Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect (if none state NONE) : NONE | |
| Is the above an existing or imminent danger to persons, Note: This is a reportable defect? | N/A |
| Is the above a defect which is not yet could become a danger to persons (if YES state the date by when) | Yes by : N/A |
| Particulars of any repair, renewal or alteration required to remedy the defect identified above : N/A | |
| Particulars of any tests carried out as part of the examination (if none state NONE) : NONE | |
| **Observation/additional comments relative to this thorough examination : Visual and functions checks conducted at the time of inspection machine was found satisfactory** | |

For confirmation scan QR code
search with report number : ESICO-LFT-R25-4014

QA/QC DEPARTMENT
EMAAR SUPPORT INSPECTION CO

Safe to operate

Next Inspection : 11-11-2025

Inspected by : Mohamed Askar Ali

INSPECTOR
C.R.: 2054100036

LEEA Full Member | أرامكو السعودية saudi aramco 10056897 | EP-Q4634 | NEOM 1100004098 | National Water Company 33564 | 10739 | sabic 001052261 | الشركة السعودية للكهرباء Saudi Electricity Company 05022531 | IAF | IAS