C.R.NO. : 4030353203
C.C.J.NO. : 324468
TEL : +966 12 655 1888
FAX : +966 12 287 7770
ISO 9001:2015

HAYKALAH
INSPECTION & TRAINING
Values For Quality

هيكلة
الفحص والتدريب
قيم الجودة

س.ت. : ٤٠٣٠٣٥٣٢٠٣
غرفة تجاره : ٣٢٤٤٦٨
هاتف : ٦٥٥ ١٨٨٨ ١٢ ٩٦٦+
فاكس : ٢٨٧ ٧٧٧٠ ١٢ ٩٦٦+
ISO 9001:2015

THIRD PARTY INSPECTION CERTIFICATE
SCISSOR LIFT

Certificate No : HIT-CRT-22-1411

Job No JO-INS-22-732

Sticker No	1460
Result	Pass

Timesheet	CL-1593
Checklist	CL-1593

Client Name & Address		Inspection Date	13-Jun-2022
Sudhir Equipment Rental Company		Expiration Date	12-Jun-2023
Jeddah		Validity	12 Month's
Kingdom of Saudi Arabia		**Types of Inspection**	
Equipment Location	Jeddah	Periodic Visual & Functional	

Equipment Description	Load Test Chart			
Scissor Lift	**Boom ↔ (Meter)**	**Radius → (Meter)**	**Test Load (Tonne)**	**S.W.L. (Tonne)**
	NA	NA	NA	NA

Load Limit (S.W.L.)	227 kg	
Serial No.	B200052642	
Model	2632-ES	
Platform Width	0.81 m	
Max Hook Capacity	NA	
Wire Rope Dia	**Main: NA**	**Aux: NA**
Boom Length	NA	
Wheel Type	Tyre	

Manufacturer	JLG
Date of Mfg.	NA
Owner ID/Plate No	SJ10ESL-249
Max Platform Height	7.77 m
Machine Weight	2,103 kg
No.of Reeve	NA
Angle of Span	NA
Person Allowed	2

Previous Inspection Details	**Next Inspection Date**	Reference Standard
NA	13-Jun-23	ASME A 90.1

Recommendation

Found satisfactory at the time of Inspection.

Authorized By: ASHADULLAH KHAN

Inspected By: KALEEM SHARIEF

Signature & Stamp

No liabilities will be considered against Haykalah Inspection Est. for failure, damage or other occurrence to client owned or operated equipment due to misuse, improper installations, poor maintenance, weather/environmental conditions & equipment operator/user mistakes or uncontrolled operation & maintenance. The concerned inspector or representative has thoroughly examined the equipment in accordance to the relevant standards. Inspection indicates that the mentioned equipment/tools/machine has no apparent defects which may prove dangerous during normal operation and it's found satisfactory for further use with provided their regular maintenance and operated by a certified operator. This certificate/report shall not be generated without an official approval in between Haykalah Inspection Est. and Client. Certificate becomes invalid if any modification/repair is made to the equipment.

6988 ABU AL ABBAS IBN ABDULMUTALIB
ASH SHAHTI DISTRICT, JEDDAH 23513-2970
KINGDOM OF SAUDI ARABIA
EMAIL: hit@hakalah.com
WEB: www.haykalah-hit.com
٦٩٨٨ ابو العباس ابن عبدالمطالب
اشاتي دستريك، جدة ٢٣٥١٣-٢٩٧٠
المملكة العربية السعودية