الشركة العالمية لخدمات التفتيش المحدودة

UNIVERSAL INSPECTION CO. LTD.

CR No. 2055011643

س.ت ٢٠٥٥٠١١٦٤٣

UKAS MANAGEMENT SYSTEMS 245 CERTIFIED ISO 9001: 2015

CERTIFICATE OF INSPECTION

Certificate No: UIC/RIY/ 20243268

Customer	:	**Sudhir Equipment Rental Company**
Location	:	Dammam, Kingdom of Saudi Arabia
Equipment	:	**Scissor Lift**
Make	:	JLG
Model	:	R4045
Serial Number	:	B200062663
ID Number	:	SJ14ESL-252
Platform Height	:	14 Meters
Reference Standard	:	**BS EN 280-1:2022**

This is to certify that the device detailed hereby have been tested against traceable International Standards for Visual Inspection on the date of inspection. These conform to manufacturer's specification and have been inspected and tested in accordance with the conditions and requirements of the contract or purchase order and unless otherwise noted below, conform in all respects to the specifications relevant here to.

Date of Inspection : 07-NOV-2024

Due Date : 06-MAY-2025

Additional Certification

Sticker Number: 209897

Inspected By:

2 INSPECTOR

Industrial Inspector

الشركة العالمية لخدمات التفتيش المحدودة ٢٠٥٥٠١١٦٤٣ UNIVERSAL INSPECTION CO. LTD. C.R. 2055011643

Approved By:

QA/QC Engineer

P.O. Box No. 2072, Jubail - 31951, K.S.A.
Tel.: +966 13 344 8882 / Fax: +966 13 344 8881
Tel.: +966 13 367 0515

www.ui.com.sa

ص.ب ٢٠٧٢، الجبيل ٣١٩٥١ - المملكة العربية السعودية
هاتف ٨٨٨٢ ٣٤٤ ١٣ ٩٦٦+ / فاكس ٨٨٨١ ٣٤٤ ١٣ ٩٦٦+
هاتف ٠٥١٥ ٣٦٧ ١٣ ٩٦٦+

sCertificate No: UIC/RIY/ 20243268

Specifications:

Platform Capacity	:	*770 lb / 349.27 kg*
Platform Capacity - Extension	:	*250 lb / 113.40 kg*
Platform Capacity - Indoor	:	*770 lb / 349.27 kg*
Platform Capacity - Outdoor	:	*550 lb / 249.48 kg*
Battery Voltage	:	*4 x 12v 150 amp-hr*
Max. Working height	:	*45 ft 3 in. / 13.79 m*
Year	:	*2020*
Machine Weight	:	*7000 lb / 3175.15 kgss*

Examination Details:

Full Operational Test	:	*Satisfactory - Battery Condition*	:	*Satisfactory*
Safety Test/Emergency Stop	:	*Satisfactory - Tilt Alarm and Light*	:	*Satisfactory*
Platform Condition	:	*Satisfactory - Lanyard Attach Points:*		*Satisfactory*
Drive Motor/Hydraulics / Tires	:	*Satisfactory - Visual Inspection*	:	*Satisfactory*
Moving Joints Lubrication	:	*Satisfactory*		

Comments & Recommendations:

- *The Scissor Lift was found to be of good working condition and reliable for safe operation*
- *On the date of Inspection we made thorough examination of the equipment specified.*
- *As far as ascertainable the equipment complied with the standard applied.*
- *On the Date of inspection the equipment found to be of Good Construction, of adequate strength, in good working order and free from apparent defects that affect safe operation.*
- *Always understand Centre of Gravity of the load & Centre of Gravity of the platform lift*
- ***Remember – Safety always comes first!***

Inspected By:

2 INSPECTOR

Industrial Inspector

UNIVERSAL INSPECTION CO. LTD. C.R. 2055011643

Approved By:

QA/QC Engineer