ZAMIL INSPECTION
شركة الزامل للمعاينة والمقاولات
Zamil Inspection & Contracting Co.
+966 55 505 2687 info@zamil.sa www.zamil.sa
Al Dhabab Avenue, King Fahad Road, Dammam, Saudi Arabia

Report No.: 21070

LIFTING EQUIPMENT INSPECTION REPORT	Area	Inspection Date	Inspection Time	Previous Sticker
	DAMMAM	03 DEC 2020	03 : 20 PM	No. 10531 | Issued By ZAMIL
Department/Contractor	Equipment Number	Equipment Location	Inspection Result	New Sticker No.
HUDHIA RENTAL	SJ12ESL-269	HUDHIA YARD	☑ Pass ☐ Fail	11169
Manufacturer	Model	Capacity / Type	Equipment Serial Number	Sticker Expiration Date
JLG / 2020	3246ES	320 KG / SCISSOR LIFT	1200033258	02 JUNE 2021

Above Equipment was inspected by ZAMIL INSPECTION AND CONTRACTING CO. in accordance with applicable Saudi Aramco G.I's, ASME and API standards. Deficiencies that require corrective action are listed below. specific repairs to correct each deficiency should be noted in the corrective action taken column.

NO.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
-	SELF PROPELLED ELEVATING WORK PLATFORM (SCISSOR LIFT) PERIODIC	
	INSPECTION, VISUAL AND FUNCTIONAL TEST WERE CARRIED OUT BASED	
	ON GI 7.030 AND ANSI / SAIA A92.6.	
-	THE RESULT FOUND SATISFACTORY DURING THE TIME OF INSPECTION.	
-	ALL THE SAFETY DEVICES ARE VERIFIED	
-	FOLLOW THE PROPER PREVENTIVE MAINTENANCE.	

RECEIVER NAME: MEHEDI HASUAN SIGNATURE: Mehedi Hasu INSPECTOR NAME: ASIF HUSSAIN KP

BADGE#: 246844647 TELEPHONE No.: 0583369987 TELEPHONE No.: 0572429766 ID-19-0006

When re-inspection is required a complete copy of this report should be ready reviewed by the inspector. Distribution: Original Proponent; 1st copy. Inspection Agency;2nd copy. Inspector