BUREAU VERITAS

BV No. 0104488

LIFTING EQUIPMENT INSPECTION REPORT	Area DAMMAM	Inspection Date FEB 16, 2022	Inspection Time —	Previous Sticker No. 21-2340 Issued By BV
Department / Contractor SUDHJR	Equipment Number S40S 6-277	Equipment Location DMM YARD	Equipment Result ☑ Pass ☐ Fail	New Sticker No. BV-21-3250
Manufacturer GENIE	Model SX-125 XC	Capacity 227KG / Type MEWP	Equipment Serial Number SX125D-798	Sticker Expiration Date AUG 15, 2022

Above Equipment was inspected by Bureaeu Veritas in accordance with applicable Saudi Aramco GI's ASME and API Standards. Deficiencies that require corrective actions are listed below. Specific repairs to correct each deficiency should be noted in the corrective action taken column.

No.	DEFECIENCIES	CORRECTIVE ACTION TAKEN
1	Periodic Inspection AND function test for	
	Boom Supported Elevating work platform.	
	As per AS Saudi Aramco GI 7.030 ANSI 92.5	
	"PASS"	

RECEIVER NAME: U BAXDALLA SIGNATURE: U Baxdalla INSPECTOR NAME: M. Omar

BADGE#: TELEPHONE No.: TELEPHONE No.: 18-0009

When re-inspection requested, a complete copy of this report should be ready review by the inspector.

Distribution: Original-Proponent, 1st Copy-2nd Copy - Inspector Agency