BUREAU VERITAS

BV No. 0107385

LIFTING EQUIPMENT INSPECTION REPORT	Area: JUBAIL	Inspection Date: DEC 12, 2022	Inspection Time: 13:00	Previous Sticker No. 14758 Issued By Bramil
Department / Contractor: SUDHJR	Equipment Number: S20S6-278	Equipment Location: JUBAIL	Equipment Result: ☑ Pass ☐ Fail	New Sticker No. BV-21-6989
Manufacturer: GENIE	Model: Z-62/40	Capacity: 227KG / Type: MEWP	Equipment Serial Number: Z62D-317	Sticker Expiration Date: JUNE 11, 2023

Above Equipment was inspected by Bureaeu Veritas in accordance with applicable Saudi Aramco GI's ASME and API Standards. Deficiencies that require corrective actions are listed below. Specific repairs to correct each deficiency should be noted in the corrective action taken column.

No.	DEFECIENCIES	CORRECTIVE ACTION TAKEN
	Periodic inspection and function test for	
	Boom supported elevating work platform	
	as per as SAMRCO GI 7.034 and SJ92.5	
	"PASS"	

RECEIVER NAME: THAISEER SIGNATURE: INSPECTOR NAME: M. Mary

BADGE#: 863 TELEPHONE No.: 0552228031 TELEPHONE No.: 18000

When re-inspection requested, a complete copy of this report should be ready review by the inspector.

Distribution: Original-Proponent, 1st Copy-2nd Copy - Inspector Agency