BUREAU VERITAS

BV No. 0104469

LIFTING EQUIPMENT INSPECTION REPORT	Area: DAMRON	Inspection Date: FEB 07, 2022	Inspection Time: —	Previous Sticker No. 21-1567 Issued By BV
Department / Contractor: SUDAIR	Equipment Number: S16AG-283	Equipment Location: ASR BASE	Equipment Result: ☑ Pass ☐ Fail	New Sticker No. BV-21-3230
Manufacturer: GENIE	Model: Z45 25RT	Capacity: 227KG / Type: MEWP	Equipment Serial Number: Z45 25D-1888	Sticker Expiration Date: AUG 06, 2022

Above Equipment was inspected by Bureaeu Veritas in accordance with applicable Saudi Aramco GI's ASME and API Standards. Deficiencies that require corrective actions are listed below. Specific repairs to correct each deficiency should be noted in the corrective action taken column.

No.	DEFECIENCIES	CORRECTIVE ACTION TAKEN
X	Periodic inspection AND Functional test for	
	Boom Supported Elevating work plat form.	
	As per AS SARAMCO GI 7.3.1 AMS 92.5	
	"PASS"	

RECEIVER NAME: UBAYDALLA SIGNATURE: [signature] INSPECTOR NAME: M. AMIR

BADGE#: TELEPHONE No.: TELEPHONE No.: 18-[illegible]

When re-inspection requested, a complete copy of this report should be ready review by the inspector.

Distribution: Original-Proponent, 1st Copy-2nd Copy - Inspector Agency