BUREAU VERITAS

BV No. 0103009

LIFTING EQUIPMENT INSPECTION REPORT	Area DAMMAM	Inspection Date DEC 08,2021	Inspection Time —	Previous Sticker No. 21-1501 Issued By BV
Department / Contractor SUDHIR	Equipment Number S22SG-284	Equipment Location DMMYARD	Inspection Result ☑ Pass ☐ Fail	New Sticker No. BV-21-3319
Manufacturer GENIE	Model S65	Capacity 227KG / Type MEWP	Equipment Serial Number S60D-1411	Sticker Expiration Date JUNE 07, 2022

Above Equipment was inspected by bureau Veritas in accordance with applicable Saudi Aramco GI's ASME and API Standards. Deficiencies that require corrective action are listed below . Specific repairs to correct each deficiency should be noted in the corrective action taken column

No.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
*	Periodic INSPection AND Function test for	
	Boom SUPPORTED elevating work plet FORM	
	AS Per AJ S. ARAMCO GI 7.030 AMSJ92-S	
	PASS	

RECEIVER NAME: Mahtab Khan SIGNATURE: MK INSPECTOR NAME: M. Sharif

BADGE#: 2420052 3982 TELEPHONE No.: 0509991738 TELEPHONE No.: 18009

When re-inspection is requested, a complete copy of this report should be ready review by the inspector

Distribution: Original-Proponent, 1st Copy - 2nd Copy - Inspector Agency