BUREAU VERITAS

BV No. 0105995

LIFTING EQUIPMENT INSPECTION REPORT	Area: TAKAJJB	Inspection Date: JAN 25, 2023	Inspection Time: 13:00	Previous Sticker No. 14620 Issued By: Zamil
Department / Contractor: SUDAJR	Equipment Number: S'26AG-285	Equipment Location: MRJN.	Equipment Result: ☑ Pass ☐ Fail	New Sticker No.: BV-21-7355
Manufacturer: GENIE	Model: Z-80/60	Capacity: 227 KG / Type: MEWP	Equipment Serial Number: Z80H-7464	Sticker Expiration Date: JULY 24, 2023

Above Equipment was inspected by Bureaeu Veritas in accordance with applicable Saudi Aramco GI's ASME and API Standards. Deficiencies that require corrective actions are listed below. Specific repairs to correct each deficiency should be noted in the corrective action taken column.

No.	DEFECIENCIES	CORRECTIVE ACTION TAKEN
*	Periodic Inspection and Function test for	
	Boom supported Elevating work platform	
	as per as S. Aramco GI 7.030, ANSI 92.5	
	"PASS"	

RECEIVER NAME: TAISSER SIGNATURE: INSPECTOR NAME: M. OMARS

BADGE#: 8031 TELEPHONE No.: TELEPHONE No.: 18009

When re-inspection requested, a complete copy of this report should be ready review by the inspector.

Distribution: Original-Proponent, 1st Copy-2nd Copy - Inspector Agency