BUREAU VERITAS

BV No. 236672

LIFTING EQUIPMENT INSPECTION REPORT	Area: JAFURA	Inspection Date: AUG 23, 2023	Inspection Time: 11:00	Previous Sticker No. 21-7743 Issued By BU
Department / contractor: SUDAIR	Equipment Number: SHOSG-296	Equipment Location: JCP-4	Equipment Result: ☑ Pass ☐ Fail	New Sticker No.: BU-21-8683
Manufacturer: GENIE	Model: SX-125XC	Capacity: 227KG / Type: MEWP	Equipment Serial Number: SX125D-565	Sticker Expiration Date: FEB 22, 2024

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI`s , ASME And API Standards. Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column.

No.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
X	Periodic inspection and function test for	
	Boom supported elevating work platform.	
	as per S.ARAMCO GI 7.036, ANSI 92.5	
	"PASS"	

RECEIVER NAME: ARIF SIGNATURE: INSPECTOR NAME: Mithun

BADGE#: TELEPHONE NO.: TELEPHONE NO.: 18

When re-inspection requested, a Complete Copy of This Report Should Be Ready For Review By The Inspector.

Distribution: Original-Proponent, 1st Copy - second 2nd Copy - Inspector Agency