07

BUREAU VERITAS

BV No. 0101964

LIFTING EQUIPMENT INSPECTION REPORT	Area: RAS ALKHAIR	Inspection Date: OCT 04, 2021	Inspection Time: —	Previous Sticker No. 21-019 Issued By BV
Department / Contractor: SUDHIR	Equipment Number: S40SG-297	Equipment Location: ARCON	Inspection Result: ☑ Pass ☐ Fail	New Sticker No.: BV-21-2607
Manufacturer: GENIE	Model: SX-125 XC	Capacity: 300 KG / Type: MEWP	Equipment Serial Number: SX125D-566	Sticker Expiration Date: APRIL 03, 2022

Above Equipment was inspected by bureau Veritas in accordance with applicable Saudi Aramco GI's ASME and API Standards. Deficiencies that require corrective action are listed below . Specific repairs to correct each deficiency should be noted in the corrective action taken column

No.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
1	Periodic Inspection and function test for	
	Boom Supported Elevating work Platform	
	As per S-ARAMCO GI 7.030 and 92-5	
	"PASS"	

RECEIVER NAME: Mahtab Khan SIGNATURE: [signature] INSPECTOR NAME: M. Osama

BADGE#: 2470523482 TELEPHONE No.: 0581849646 TELEPHONE No.: 18-009

When re-inspection is requested, a complete copy of this report should be ready review by the inspector

Distribution: Original-Proponent, 1st Copy - 2nd Copy - Inspector Agency