REPORT OF VISUAL EXAMINATION

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998

Client Name & Address:	SUDHIR EQUIPMENT RENTAL COMPANY -RAS ALKHAIR		
Work Order No.	ZAM-3387-09-23	**Report No.**	ZAMIL-R03904 / VIS
Place Of Inspection	RAS ALKHAIR SUDHIR	**Report Date**	19/09/2023
Date of Last Inspection	25/07/2023	**Date of Inspection**	18/09/2023
Customer Requisition No.	N/A	**Date of Next Inspection**	17/03/2024
Applicable Standards	ANSI A92-5	**Issued Sticker No.**	N/A
O.E.M / C.O.C No. / Drawings	Available	**Color Code (If Applicable)**	NA
Equipment Used	VERNIER CALIBER & CAMERA	**Model No.**	1350SJP

Equipment Serial No.	Equipment I.D	QTY	Description	Capacity/SWL (Ton)
0300256993	S43SJP-302	01	Man Lift Diesel Powered Articulated Boom Supported Personnel Elevating Work Platform Max Capacity : 1000 LBS Max Platform Height : 135 FT Max Horizontal Reach : 80 FT Manufacturer : JLG Industrial INC Machine Weight : 44610 LBS Year Of Manufacturer : 2019 Note : Visual inspection and functional test has been performed on the above mentioned equipment, during the time of inspection no any abnormality found.	1000 LBS

Is this the first examination after installation or assembly at a new site or location:	☐ YES ☑ NO
If the answer to the above question is YES. Has the equipment been installed correctly?	☐ YES ☐ NO ☑ NA
Was the thorough examination carried out Within an interval of 3 months?	☐ YES ☑ NO
Was the thorough examination carried out Within an interval of 6 months?	☑ YES ☐ NO
Was the thorough examination carried out Within an interval of 12 months?	☐ YES ☑ NO
In accordance with an examination scheme?	☑ YES ☐ NO
After the occurrence of exceptional circumstances?	☐ Yes ☑ No
Identification of any part found to have a defect which is or could become a danger to person and a description of the defect (if none state none): NONE	
Is the above a defect which is of immediate danger to persons	☐ YES ☑ NO
Is the above a defect which is not yet but could become a danger to persons? (If yes state the day by when)	☐ YES ☑ NO Date: N/A
Particulars of any repair, renewal or alteration required to remedy the defect identified above: **NONE**	
Particulars of any tests carried out as part of the examination: (If none state NONE): **NONE**	
Inspection Result:	**During the time of Inspection** Result found satisfactory **- Is this Equipment Safe to Operate?** ☑ YES ☐ NO

This certificate by company under its general conditions of services. This issuance of this certificate does not exonerate the buyers or sellers from exercising all their rights discharging all their liabilities under the contacts of sale. Stipulations to contrary are not binding on the company's responsibility under this certificate is limited to proven negligence and will in no case be more than ten times the amount of the free or commission. The above findings are limited to date place of intervention only. The company is neither an insurer not a guarantor disclaims all liabilities in such capabilities.

Inspected By Qualified: LEEA & ASNT NDT Level II		Reviewed By		Stamp
Name:	Ahmed Rashad	**Name:**	Mohamed Atwa	QA/QC DEPARTMENT ZAMIL INSPECTION Reviewed By
Position:	Inspector	**Position:**	Technical supervisor	
Signature:		**Signature:**		

Name and address of employer of persons making and authenticating this report: Zamil Inspection & Contracting Co, King Fahad Road–Al-Dhabab Avenue–Dammam 32261
C.R.: 2050069798–Email: operations@zamil.sa

Zamil Inspection & Contracting Co.

+966555052687 info@zamil.sa

NO. ZAM-W-14980

Equipment Type	:	Man Lift
capacity/SWL	:	1000 LBS
Equipment ID	:	S43SJP-302
Equipment S.N.	:	0300256993
Inspection Date	:	18/09/2023
Next Insp Date	:	17/03/2024
Inspected By	:	Ahmed Rashad