BUREAU VERITAS

BV No. 0104555

LIFTING EQUIPMENT INSPECTION REPORT	Area DAMMAM	Inspection Date FEB 23, 2022	Inspection Time —	Previous Sticker No. 12382 Issued By Bilal
Department / Contractor SUDAIR	Equipment Number S43SJP-303	Equipment Location DMM YARD	Equipment Result ☑ Pass ☐ Fail	New Sticker No. BU-21-3260
Manufacturer JLG	Model 1350 SJP	Capacity 500LBS / Type MEWP	Equipment Serial Number 0300254474	Sticker Expiration Date AUG 22, 2022

Above Equipment was inspected by Bureaeu Veritas in accordance with applicable Saudi Aramco GI's ASME and API Standards. Deficiencies that require corrective actions are listed below. Specific repairs to correct each deficiency should be noted in the corrective action taken column.

No.	DEFECIENCIES	CORRECTIVE ACTION TAKEN
*	Periodic Inspection and Function test for	
	Boom Supported Elevating work platform	
	As per as Saudi Aramco GI 7.031, ANSI 92.5	
	"PASS"	

RECEIVER NAME: UBAID ALLA SIGNATURE: INSPECTOR NAME: Nwamora

BADGE#: TELEPHONE No.: TELEPHONE No.: 18-0009

When re-inspection requested, a complete copy of this report should be ready review by the inspector.

Distribution: Original-Proponent, 1st Copy-2nd Copy - Inspector Agency