



PRESERV BUILDING RESTORATION MANAGEMENT, INC.

PROVIDING INNOVATIVE BUILDING SOLUTIONS SINCE 1993

DAILY JOB REPORT

Project Information	
Project Address:	601 W 110th St
PM/PS:	Michael / Carlos
Date:	01/01/2024
Person Filing Report:	Nathanael
Weather:	L 39 H 45 overcast clouds

Job Information	
Number of workers onsite:	15
Other Visitors Onsite: (Client, architect, etc)	
Work taking place onsite: (type, location, drawing/façade)	Roof
Materials Needed for the Week:	
Subcontractors Onsite:	MDV

