



TO
N/A

INSPECTION NUMBER
N/A

DATE
29-12-2025

Car Options

Make	Mahindra	Model	KUV 100
Year	01-01-1970	Color	White
VIN #	MA1VD2NACH6061027_	Engine Size	1.2 cc
Specs	N/A	Odometer	KM
Transmission	Manual	Roof	N/A
Inspection Date	29-12-2025	Valuation Price	ZAR N/A
Warranty Plan	No	Fuel Type	Diesel
Warranty Plan Until		Service Plan	N/A



Detailed Inspection Report

Complete vehicle condition assessment


Handling	Okay	Road Test	Okay
Cylinder Leakage	Okay	Diagnostics	Faulty
Gear Linkages	Okay	Gear Selector	Faulty
Auto Transmission	No Visible Leaks	Gear & Diff Oil	No Visible Leaks
Clutch Cable	Okay	Clutch Slave	Okay
Brake Hose	Okay	Brake Calipers	Okay
Hand Brake	Okay	Brake Master Cylinder	Okay
Front Brake Pads		Rear Brake Pads	




Inspection Images

Vehicle exterior documentation


FRONT



LEFT SIDE



RIGHT SIDE



REAR

