
Technical Exhibit: DPG Site-Specific UST & LUST Management

This exhibit details the specific assets, locations, and coordination requirements for UST operations at U.S. Army Dugway Proving Ground.

1. Regulated Asset Inventory (Facility Table)

The Contractor is responsible for the comprehensive management of the following 13 regulated USTs across five (5) Facility IDs:

Facility ID	Location Name	Qty / Type of Tank	Primary Use
#8000048	US Army DPG	5 USTs (1 in Temp Closure)	Emergency Generators
#8000121	AAFES Service Station	3 UNL / 1 Diesel	Public Fueling
#8000122	English Village (EV) Motor Pool	1 UNL / 1 Diesel	GSA Vehicle Fueling
#8000123	Ditto Motor Pool (DMP)	1 UNL / 1 Diesel	GSA Vehicle Fueling
#8000154	Security Bldg Ditto 4515	1 UST	Emergency Generat

Annual UST Compliance Metrics

- **13 Leak Detection Tests:** Verification of functionality for 100% of the leak detection systems (probes, sensors, and ELLDs) across all 13 tanks to ensure they can detect a leak of **0.1 gallons per hour (gph)**.
- **26+ Spill & Overfill Inspections:** Visual and functional testing of at least **13 spill buckets** and **13 overfill prevention devices** (flapper valves or ball floats) to ensure they are clear of liquid/debris and engage at **95% capacity**.
- **5 Facility Certification Renewals:** Completion of 100% of the paperwork and fee processing for the **5 Utah DERR Facility IDs** to secure the annual "Certificate of Compliance" for the installation.
- **1 LUST Site Monitoring Event:** Collection and analysis of groundwater/soil samples at the **Ditto Motor Pool** LUST site, typically involving **3 to 8 monitoring wells** (depending on the DERR-approved plan) to track contaminant trends.

- **156 Monthly Inspections (Aggregated):** Execution of **12 monthly "Walk-through" inspections** for each of the **13 tanks**, documenting sensor status, logbooks, and any signs of surface release or equipment tampering.