

Refuge location:

Name:

Flint Hills NWR

Address:

530 West Maple Ave

Hartford, Kansas

Phone number:

620-481-0865

Point of contact information:

T. J. Cooper

FBMS Equipment #: 10124599

Make: John Deere

Model: 6125R

Year: 2014

Serial number: 1L06125RAEH803799

Hours: 1509

Requested replacement:Glass/Windows
Seat/Upholstery

Good	Fair	Poor	N/A
------	------	------	-----

	X		
	X		

Transmission
3 point
PTO

Good	Fair	Poor	N/A
------	------	------	-----

	X		
X			
	X		

*Leaks:*Engine
Transmission
Axle seals

Yes	No	N/A
-----	----	-----

*Operable:*Lights
Gauges
Heater
Air conditioning

Good	Fair	Poor	N/A
------	------	------	-----

		X	
	X		
X			
X			

*Tire depth:*Front
Rear
Duals

Good	Fair	Poor	N/A
------	------	------	-----

		X	
	X		
			X

Good	Fair	Poor
------	------	------

	X	
--	---	--

Overall condition:**Known issues/concerns:**

Last 2 pictures show some body damage on both lower sides around the fuel tank. Has been used for heavy mowing. Handle of shifter has the rubber decentigrated.