




File: P15 Drawing  
 Project: 636A6-26-102 Replace Building 2 Condensate Leak  
 Location: VA Central Iowa Health Care System  
 Building(s): 1-4  
 Floor(s): Basement