

GeoAI Field Survey Report

Project: Musanada Asset Verification | Date: 10 June 2025 | Team: Survey Unit B

1. Survey Objectives

This report documents the results of a field verification survey conducted to confirm the physical extent, condition, and boundary coordinates of six (6) asset parcels within the Musanada portfolio cluster located in Mussafah Industrial Area, Abu Dhabi. All coordinates collected using Trimble R10 GNSS receiver, accuracy ± 5 cm.

2. Survey Station Coordinates

Station	Asset Name	Latitude (°N)	Longitude (°E)	Elevation (m)	Method	HDOP
S-001	Warehouse Alpha	24.465312	54.371840	18.4	RTK-GNSS	0.8
S-002	Admin Block NW	24.466801	54.373245	17.2	RTK-GNSS	0.9
S-003	Admin Block SE	24.464100	54.373198	18.1	RTK-GNSS	1.0
S-004	Storage Yard A	24.462340	54.370120	19.0	RTK-GNSS	0.7
S-005	Storage Yard B	24.462980	54.368450	18.7	RTK-GNSS	0.8
S-006	Guard Post	24.464560	54.369870	18.3	Static-GPS	1.2
S-007	Main Gate	24.466020	54.370340	17.8	RTK-GNSS	0.6
S-008	Utility Block	24.463780	54.372560	18.5	RTK-GNSS	0.9

3. Polygon Boundary — Warehouse Alpha

The following ring defines the boundary polygon for Warehouse Alpha (Plot WH-101). Vertices listed in order; ring is closed (first point repeated at end).

Vertex	Longitude (°E)	Latitude (°N)	Note
V1	54.371840	24.465312	SW corner — main gate post
V2	54.373100	24.465290	SE corner — boundary wall
V3	54.373120	24.466750	NE corner — perimeter fence
V4	54.371820	24.466780	NW corner — adjacent road
V1	54.371840	24.465312	Closure point (= V1)

4. Field Observations

Asset	Field Notes
Warehouse Alpha	Active — 24/7 operations. Boundary fence intact. Loading dock on south side.
Admin Block	Active — office hours only. New extension under construction on east wing.
Storage Yard A	Partially active. Some sections used for overflow parking.
Storage Yard B	Inactive. Vegetation encroachment on north boundary. Fencing damaged in 2 places.
Guard Post	Active — 24/7 staffing. Coordinates match cadastral records.
Utility Block	Active. Substation and pump room. Access restricted.

5. Summary

All 8 survey stations were occupied successfully. Coordinate data has been uploaded to the GeoAI system for map display and portfolio tracking. Two boundary discrepancies noted at Storage Yard B require follow-up with the Land Department. Signed: Survey Lead Engineer, Musanada Technical Division, June 2025.