

Inspection #:

## QUALITY Inspection Report

Frac Co.	
Operator	

					moposiion report						<b>Operato</b> .					
Make:	N	lodel:		Seria	Serial #:					ipme	ent #	<b>#</b> :				
Inspection: Check if ac	ceptable	in accordar	nce with Complia	ance Se	rvices			•								
			Inspection	on #:	1	2	3	4	5	6	7	8	9	10	11	12
All functions operate properly				<b>√</b>	<b>√</b>	<b>√</b>	✓	<b>√</b>	<b>√</b>	1	<b>√</b>	<b>√</b>	<b>√</b>	<b>√</b>	<b>√</b>	
Structure and components secure and undamaged				<b>√</b>	<b>√</b>	✓	1	✓	<b>√</b>	1	1	<b>√</b>	✓	✓	✓	
Shower and eyewash intact and functional				1	✓	✓	✓	✓	✓	1	1	<b>√</b>	✓	<b>√</b>	✓	
Operational and safety decals present and legible				1	<b>√</b>	<b>√</b>	1	1	<b>√</b>	1	<b>√</b>	1	<b>√</b>	<b>√</b>	<b>√</b>	
Batteries Charged				✓	✓	✓	✓	✓	✓	1	1	✓	✓	<b>√</b>	✓	
Electrical cord/plug				✓	✓	✓	✓	✓	✓	1	1	✓	✓	✓	✓	
Containment tank Qty Pumps:				✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
Appearance accep	otable				<b>√</b>	✓	✓	✓	✓	✓	1	1	✓	✓	✓	✓
Fire Extinguisher (	Qty:				✓	✓	✓	✓	✓	✓	1	1	✓	✓	✓	✓
First Aid				✓	✓	✓	✓	✓	✓	1	✓	✓	✓	✓	✓	
Ma	anufac	ture/Mod	del		•	•		•	,		•	•	•	•	•	•
AED					<b>√</b>	✓	✓	✓	<b>√</b>	✓	<b>√</b>	<b>√</b>	✓	✓	✓	✓
S/N Pad Exp.			Battery Exp.						Placed in Service							
Inspection Notes:										ſi	Emp	loye	е	Dat	e	
Inspection #:																
Inspection #:																
Inspection #:																
Inspection #:																
Inspection #:																
Inspection #:																
Inspection #:																
Inspection #:																
Inspection #:																
Inspection #:																
Inspection #:																