UptimeEquip
Flexible Innovative Packaging Systems

SelectEquip
Flexible Innovative Packaging Systems

GENERAL SERVICE REPORT

Customer:	Liteneasy WA	**Date:**	05/12/2022
Site Address:		**Site Contact:**	Sean
		Phone:	
Customer PO #:		**Internal Job #:**	SR2484
Subject: Bellow broken on the lunch tool.			

Equipment Type:	**Serial Number:**	**Customer Line # (if applicable):**
Trave 350 VG	A/17/A-11559	Line 1
Trave 350 VG	A/17/A-11558	Line 2

Equipment condition:

Excellent

Work Performed:

Arrived onsite and replaced the broken bellow on the tool as discussed with Sean..

SPARE PARTS USED				
Part Number:	**Description:**	**Qty:**	**Chargeable?**	
			Yes☐	No☐

RECOMMENDED SPARE PARTS		
Part Number:	**Description:**	**Qty:**

STATUS		
Machine Tested?	Yes☒	No☐
Comments:		
Revisit Required?	Yes☐	No☒
Comments:		

RECOMMENDATIONS
Comments:

Select Equip
7 Gatwick Road Bayswater North
Victoria 3153 Australia
Phone +61 (3) 8720 8400

Trading as Select Equip
Select Packaging Systems Pty Ltd ABN 59 087 731 520
spares@selectequip.com.au www.selectequip.com.au

GENERAL SERVICE REPORT

TECHNICIAN HOURS					
Time	**05/12/2022Start**	**05/12/2022Finish**			
Travel To Site:	10:30	11:00			
Onsite:	11:00	12:00			
Travel From Site:	12:00	12:45			

REPORT SIGN OFF			
	Print Name:	**Signature:**	**Date:**
Customer:	Sean	X	05/12/2022
Technician:	Bertus Reynolds		