UptimeEquip
Innovative Maintenance Support Program

SelectEquip
Flexible Innovative Packaging Systems

GENERAL SERVICE REPORT

Customer:	Lite and Easy	**Date:**	07/05/2025
Site Address:	8-10 Naweena Road Regency Park	**Site Contact:**	Peter
		Phone:	0417782039
Customer PO #:		**Internal Job #:**	5405

Subject: Seeling issue with lunch tool

Equipment Type:	Serial Number:	Customer Line # (if applicable):
Trave 340		Line 1

Equipment condition:

Excellent Condition

Work Performed:

- Arrived on site and found line already running. Check operators if they had any issue during start-up or in the run so far. They said all was good with start-up and did not have any issue so far.
- I monitored production for 3 hours to see different products and trays sizes.
- I had to make a small adjustment to gas level as the trays with less product in them was slightly flat. Updated recipe and saved change
- During the production run we not have any issue with sealing or pre-cutting at all and the line ran very well.
- There were some reworks due to product contamination on the flange of the tray.

SPARE PARTS USED

Part Number:	Description:	Qty:	Chargeable?	
			Yes ☐	No☐
			Yes☐	No☐
			Yes☐	No☐

STATUS

Machine Tested?	Yes☒	No☐
Comments: Ran trays filled with tomato's		
Revisit Required?	Yes☐	No☐
Comments:		

RECOMMENDATIONS

Select Equip
7 Gatwick Road Bayswater North
Victoria 3153 Australia
Phone +61 (3) 8720 8400

Trading as Select Equip
Select Packaging Systems Pty Ltd ABN 59 087 731 520
spares@selectequip.com.au www.selectequip.com.au

UptimeEquip
Innovative Maintenance Support Program

SelectEquip
Flexible Innovative Packaging Systems

GENERAL SERVICE REPORT

Comments:

TECHNICIAN HOURS	**David van der Merwe**	
Time	**Start**	**Finish**
Travel To Site:	5:00	6:00
Onsite:	6:00	9:00
Travel From Site:	9:00	10:00
Remote assistance:		
Report writing:	10:30	11:00
Overnight stay	☐	
Overnight stay with flights	☐	

REPORT SIGN OFF			
	Print Name:	**Signature:**	**Date:**
Customer:	Peter	X	07/05/2025
Technician:	David		