UptimeEquip
Innovative Maintenance Support Program

SelectEquip
Flexible Innovative Packaging Systems

GENERAL SERVICE REPORT

Customer:	Lite and Easy	**Date:**	07/09/2024
Site Address:	8-10 Naweena Road Regency Park	**Site Contact:**	Mark
		Phone:	0439843714
Customer PO #:		**Internal Job #:**	4837

Subject: Replace top tool vacuum supply hose.

Equipment Type:	Serial Number:	Customer Line # (if applicable):
Trave 340	11558	Line 2

Equipment condition:

Excellent Condition

Work Performed:

- Arrived on site and met with Henry.
- Removed old hose from line and replace with new hose.
- Replaced one of the hose clamps as it was not tightening correctly.
- Swapped out transfer belt for dinner tool and preformed vacuum test.
- Dry cycled machine to check vacuum during cycle.
- Installed transfer belt back in the machine so it is ready for production on Monday.

SPARE PARTS USED

Part Number:	Description:	Qty:	Chargeable?	
			Yes ☐	No☐
			Yes☐	No☐
			Yes☐	No☐

STATUS

Machine Tested?	Yes☒	No☐
Comments: Vacuum test and dry cycle machine		
Revisit Required?	Yes☐	No☒
Comments:		

RECOMMENDATIONS

Select Equip
7 Gatwick Road Bayswater North
Victoria 3153 Australia
Phone +61 (3) 8720 8400

Trading as Select Equip
Select Packaging Systems Pty Ltd ABN 59 087 731 520
spares@selectequip.com.au www.selectequip.com.au

UptimeEquip
Innovative Maintenance Support Program

SelectEquip
Flexible Innovative Packaging Systems

GENERAL SERVICE REPORT

Comments:

TECHNICIAN HOURS	**David van der Merwe**	
Time	**Start**	**Finish**
Travel To Site:	7:15	8:00
Onsite:	8:00	8:30
Travel From Site:	8:30	9:15
Remote assistance:		
Report writing:	9:15	9:45
Overnight stay	☐	
Overnight stay with flights	☐	

REPORT SIGN OFF			
	Print Name:	**Signature:**	**Date:**
Customer:	Mark	X	07/09/2024
Technician:	David		

Select Equip
7 Gatwick Road Bayswater North
Victoria 3153 Australia
Phone +61 (3) 8720 8400

Trading as Select Equip
Select Packaging Systems Pty Ltd ABN 59 087 731 520
spares@selectequip.com.au www.selectequip.com.au