UptimeEquip
Flexible Innovative Packaging Systems

SelectEquip
Flexible Innovative Packaging Systems

GENERAL SERVICE REPORT

Customer:	Liteneasy WA	**Date:**	09/09/2022
Site Address:		**Site Contact:**	Jaspreet / Sean
		Phone:	
Customer PO #:		**Internal Job #:**	SR
Subject: Correct a few discrepancies as reported by Sean			

Equipment Type:	Serial Number:	Customer Line # (if applicable):
Trave 350 VG	A/17/A-11559	Line 1
Trave 350 VG	A/17/A-11558	Line 2

Equipment condition:

Excellent

Work Performed:

Arrived onsite and tested the dinner tool that was reported faulty. The tool measured correct and I tested the tool on the machine.

Sean showed me bolts missing on the bottom tool counter tool. I obtained new bolts and drilled out one bolt that was broken off. I re-tapped the hole and installed all bolts.

I also repaired the tool trolley.

SPARE PARTS USED

Part Number:	Description:	Qty:	Chargeable?	
			Yes☒	No☐
			Yes☐	No☐

STATUS

Machine Tested?	Yes☒	No☐
Comments:		
Revisit Required?	Yes☒	No☐
Comments:		

RECOMMENDATIONS

Comments:

TECHNICIAN HOURS

Time	Start	Finish		Start	Finish
Travel To Site:	12:30	13:00			
Onsite:	13:00	16:30			
Travel From Site:	16:30	17:30			

REPORT SIGN OFF

Select Equip
7 Gatwick Road Bayswater North
Victoria 3153 Australia
Phone +61 (3) 8720 8400

Trading as Select Equip
Select Packaging Systems Pty Ltd ABN 59 087 731 520
spares@selectequip.com.au www.selectequip.com.au

GENERAL SERVICE REPORT

	Print Name:	Signature:	Date:
Customer:	Sean/Jaspreet	X _____	09/09/2022
Technician:	Bertus Reynolds		

Select Equip
7 Gatwick Road Bayswater North
Victoria 3153 Australia
Phone +61 (3) 8720 8400

Trading as Select Equip
Select Packaging Systems Pty Ltd ABN 59 087 731 520
spares@selectequip.com.au www.selectequip.com.au