UptimeEquip
Flexible Innovative Packaging Systems

SelectEquip
Flexible Innovative Packaging Systems

GENERAL SERVICE REPORT

Customer:	Hilton foods Truganina	**Date:**	12th August
Site Address:	Victoria Melbourne	**Site Contact:**	George Karagounis
		Phone:	048702 2551
Customer PO #:		**Internal Job #:**	5618

Subject: Tool Paper tool

Equipment Type:	Serial Number:	Customer Line # (if applicable):
Paper skin tool		Line 2 Trave 590

Equipment condition:

Work Performed:

Thursday 31st

Line 2 Paper skin tool

- *Arrived on site and started to on the paper skin tool but was asked to solve other problems*
- *Line 3 kept coming up with tool down error and we needed to activate to clear error.*
- *Line 3 medium tool needed to be pulled out and inspected, Gabriel found the seal bars loose mostly on the exit side, once this we tightened and floating shafts they were able to run, Gabriel stayed late to get them running.*
- *Line 5 recipe had to be saved due to some changes done to spacer belt positioning.*
- *Line 15 was not sealing, we had to remove the tool to inspect the sealbar which were fully contaminated and had no Teflon.*
- *Once the sealbars were cleaned we manage to get the line up and running at 115ppm on small.*
- *Line 17 was inspected and running too hot at 210C but found the sealbars were contaminated and needed to be cleaned.*

Spend all day on problem solving and not on the paper tool.

TECHNICIAN HOURS	**Marc Ashford**	
Time	**Start**	**Finish**
Travel To Site:	05:00	09:30
Onsite:	09:30	16:00
Travel From Site:	16:00	16:30
Remote assistance:		
Report writing:	15min	
Overnight stay	☐	
Overnight stay with flights	☒	

REPORT SIGN OFF			
	Print Name:	**Signature:**	**Date:**
Customer:		X _____	12th August
Technician:	Marc Ashford		

Select Equip
7 Gatwick Road Bayswater North
Victoria 3153 Australia
Phone +61 (3) 8720 8400

Trading as Select Equip
Select Packaging Systems Pty Ltd ABN 59 087 731 520
spares@selectequip.com.au www.selectequip.com.au