UptimeEquip
Innovative Maintenance Support Program

SelectEquip
Flexible Innovative Packaging Systems

GENERAL SERVICE REPORT

Customer:	Lite and Easy	**Date:**	26/09/2024
Site Address:	8-10 Naweena Road Regency Park	**Site Contact:**	Mark
		Phone:	0439843714
Customer PO #:		**Internal Job #:**	4873

Subject: Line 1 safety not resetting.

Equipment Type:	Serial Number:	Customer Line # (if applicable):
Trave 340		Line 1

Equipment condition:

Excellent Condition

Work Performed:

- Arrived on site and met with Henry.
- Inspected safety system and found none operator side safety is blinking and system not resetting.
- Started test and tracing wiring to find which safety switch is causing the issue.
- Found on that the operator side safety is not switching correctly.
- Swapped sensor out to see if the sensor is faulty but problem still there.
- Isolated machine and removed safety sensor cable. Found insulation broken and a lot of moisture present.
- Replaced cable and test
- Cable tied cables neatly and monitor production start-up

SPARE PARTS USED

Part Number:	Description:	Qty:	Chargeable?

Select Equip
7 Gatwick Road Bayswater North
Victoria 3153 Australia
Phone +61 (3) 8720 8400

Trading as Select Equip
Select Packaging Systems Pty Ltd ABN 59 087 731 520
spares@selectequip.com.au www.selectequip.com.au

UptimeEquip
Innovative Maintenance Support Program

SelectEquip
Flexible Innovative Packaging Systems

GENERAL SERVICE REPORT

			Yes ☐	No☐
			Yes☐	No☐
			Yes☐	No☐

STATUS		
Machine Tested?	Yes☒	No☐
Comments: Vacuum test and ran production		
Revisit Required?	Yes☐	No☒
Comments:		

RECOMMENDATIONS
Comments:

TECHNICIAN HOURS	**David van der Merwe**	
Time	**Start**	**Finish**
Travel To Site:	8:00	8:45
Onsite:	8:45	10:00
Travel From Site:		
Remote assistance:		
Report writing:	15:00	15:30
Overnight stay	☐	
Overnight stay with flights	☐	

REPORT SIGN OFF			
	Print Name:	**Signature:**	**Date:**
Customer:	Mark	_X_____	26/09/2024
Technician:	David		