UptimeEquip
Innovative Maintenance Support Program

SelectEquip
Flexible Innovative Packaging Systems

GENERAL SERVICE REPORT

Customer:	Bindaree Beef	**Date:**	03/10/2025
Site Address:	6 Taree Street Burleigh Heads	**Site Contact:**	Joseph Brown
		Phone:	0434077565
Customer PO #:		**Internal Job #:**	5744

Subject: Line 2 breakdown – Mince belt not running

Equipment Type:	Serial Number:	Customer Line # (if applicable):
Trave 590VGXL-S	A21/A12629	Line 2

Equipment condition:

Work Performed:

- Called onsite due an issue with the top meat supply belt not running.
- Upon arriving onsite and reviewing the motor screen page, based on the client's previous checks, we suspected that the drive was faulty not supplying the voltage required to start the motor.

- Replaced the drive and the belt started run again
- Some concerns why the drive wasn't giving any fault which will be investigated a later stage.

SPARE PARTS USED

Part Number:	Description:	Qty:	Chargeable?	
			Yes ☐	No☐
			Yes☐	No☐
			Yes☐	No☐

Select Equip
7 Gatwick Road Bayswater North
Victoria 3153 Australia
Phone +61 (3) 8720 8400

Trading as Select Equip
Select Packaging Systems Pty Ltd ABN 59 087 731 520
spares@selectequip.com.au www.selectequip.com.au

UptimeEquip
Innovative Maintenance Support Program

SelectEquip
Flexible Innovative Packaging Systems

GENERAL SERVICE REPORT

STATUS		
Machine Tested?	Yes☒	No☐
Comments: Good		
Revisit Required?	Yes☐	No☐
Comments:		

RECOMMENDATIONS
Comments:

RECOMMENDED SPARE PARTS		
Part Number:	**Description:**	**Qty:**

TECHNICIAN HOURS	Jacques	
Time	**Start**	**Finish**
Travel To Site:	09:30	11:30
Onsite:	11:30	14:00
Travel From Site:	14:30	16:00
Remote assistance:	0	
Report writing:	30 Min	
Overnight stay	☐	
Overnight stay with flights	☐	

REPORT SIGN OFF			
	Print Name:	**Signature:**	**Date:**
Customer:	Joseph Brown	X _____	03/10/2025
Technician:	Gianpaolo Orisio		