UptimeEquip
Flexible Innovative Packaging Systems

SelectEquip
Flexible Innovative Packaging Systems

MONDINI TECHNICAL SERVICE ROUTINE

CUSTOMER:	Huon Aquaculture	**DATE:**	08-12-2022
ADDRESS:	Tasmania	**CONTACT:**	Anthony
		MACHINE NO:	A14A-00911

Equipment type/s:	E340	**Machine Cycles:** 1531500	**Push Cycles:** 1531606
Product description:	9x7 and 9x5		**Run Time:** 8123328
Was the machine running before the service?	Yes	No	**Comments:** Line dirty

Description	Comment	OK	Description	Comment	OK
Belts , Cords and Rollers			**Under Machine**		
Condition of Infeed belt		☑	Main motor brake adjustment 0.3 mm	Servo motor	☐
Condition of spacer belt		☑	Pusher motor brake adjustment		☑
Check Phasers and Guides	N/A	☐	All Sensors Tight and operational		☑
			All Rod ends Tight		☑
Condition of out feed cords		☑	Check Air and gas system		☑
Check Bearings		☑	Main lifter gearbox fluid level		☑
Check Sensors / Reflectors		☑	Pusher Arm gearbox fluid level		☑
Inspection and adjustments of Timing Belts			Lubricate all Lube points		☑
Infeed		☑	Check filter vacuum Pump		☐
Spacer		☑	**Infeed Chain**		
Outfeed		☑	Check all sprockets &Lubricate		☑
Track Belts		☑	Check chain line Tension		☑
Film			Check Condition of Chain Lugs		☑
Check position of spreader cones	Not installed	☐	Check Operation of start/stop E-stop	Lot of water	☑
Check scrap rewind tension		☑	**Lifting Plate**		
Check condition of Airshafts		☑	Change O'Rings	Replaced	☑
Check condition of film path rollers		☑	Check hoses of Gas & Vacuum		☑
Check tracking of rollers		☑	Check height of mobile plate	N/A	☐
Check air leaks		☑	Check upper slides for Nylon	Missing	☑
Film – Film Advance			Check solenoids		☑
Nylon gears		☑	Check doors and door locks		☑
Roller&Bearings	Replaced	☑	**Electrical**		
Check nylon bushing on film break		☑	Inspect Electrical Cabinet for loose		☑
Rubber Roller	Need to be replaced	☑	Check discoloured (hot) connections		☑
Breaking sensor		☑	Check All switches		☑
Film – Reel Unwind			Check operation of machine Interface		☑
Airshalft for leaks		☑	Battery of PLC		☐
O-Cord Condition		☑	Battery of machine Interface		☐
Film Path			Infeed Timing and Setup		☑
Operation of dancers		☑	Check Phasers Alignment	N/A	☐
Pendulum		☑	**Reset all Alarms)**		☑
Sensors		☑	**Test Run Machine (with Product**	Dry Cycle	☑
Photo cell for printed film	N/A	☐	**If applicable**		

UptimeEquip
Flexible Innovative Packaging Systems

SelectEquip
Flexible Innovative Packaging Systems

TOOL SERVICE ROUTINE

CUSTOMER: Huon Aquaculture
ADDRESS: Tasmania
DATE: 08/12/2022
CONTACT: Anthony
MACHINE NO: A14A-00911

Equipment type/s:	Trave 340		Trave 340					
Tool Number (STS)	SB-138-550		A90972					
Tray Size	9x7		9x5					
Description	**Comment**	**OK**	**Comment**	**OK**	**Comment**	**OK**	**Comment**	**OK**
Top Tooling								
Cleanliness	Cleaned	☑	Cleaned	☑		☐		☐
Knives		☑	Need to be replaced	☑		☐		☐
O'Cord	Replaced	☑	Replaced	☑		☐		☐
Straightness of film blocking Area		☑		☑		☐		☐
Springs (Main) / Heater Plate		☑		☑		☐		☐
Lubrication	Yes	☑	Yes	☑		☐		☐
Inspect Bellows		☑		☑		☐		☐
Check general condition		☑		☑		☐		☐
Check seal bars	Worn	☑	Cleaned	☑		☐		☐
Resistance check on elements	14 ohm	☑	14 ohm	☑		☐		☐
Check probe (PT100)	107 ohm	☑	105 ohm	☑		☐		☐
Bottom Tool								
Check Cleanliness	Cleaned	☑	Cleaned	☑		☐		☐
Check T Section (change if necessary)	Replaced	☑	Replaced	☑		☐		☐
Tighten Foot Plate		☑		☑		☐		☐
Lubricate	Yes	☑	Yes	☑		☐		☐
Replace O'Rings (4)	Replaced	☑	Replaced	☑		☐		☐
Check Spring Length		☑	Replaced	☑		☐		☐
Check O'Cords		☑		☑		☐		☐
Check Dampers		☑		☑		☐		☐
Check general condition		☑		☑		☐		☐

General Comments	Comments Tool 1	Comments Tool 2	Comments Tool 3	Comments Tool 4
	Seal bars worn.	Tool was dirty		

Service Technician: David van der Merwe **Date:** 08/12/2022

(Print Name) (Signature)

Select Equip
7 Gatwick Road Bayswater North
Victoria 3153 Australia
Phone +61 (3) 8720 8400 AH 03 9761 7989

Trading as Select Equip
Select Packaging Systems Pty Ltd ABN 59 087 731 520
sales@selectequip.com.au www.selectequip.com.au