VEHICLE DAMAGE ASSESSMENT REPORT

Certified Computer Vision & Deep Learning AI Estimate

VEHICLE DETAILS

Manufacturer: Hyundai
Model: Creta
Manufacturing Year: 2023
Registration Number: MH-12-AB-1234

INSPECTION SUMMARY

Images Analyzed: 1 (360° Multi-View)
Damaged Components: 2
Minor Damage: 0 | **Moderate:** 1 | **Severe:** 1
AI Fusion Status: Multi-angle duplicates consolidated

DAMAGED COMPONENTS & REPAIR BREAKDOWN

Vehicle Part	Damage Type	Severity	Area %	Action	Parts Cost	Labor	Total
Front Bumper	Scratch	Minor	28.5%	Paint/Repair	■3,280	■1,890	■5,170
Headlight (Right)	Crack	Severe	28.5%	Replace	■26,320	■3,380	■29,700

Total Parts Cost:	**■29,600**	**ESTIMATED TOTAL REPAIR COST:**	**■34,870**
Total Labor Cost:	**■5,270**	**Estimated Range (95% CI):**	**■30,700 – ■39,800**

DISCLAIMER: This assessment is generated using Computer Vision (YOLOv8/11, Segmentation) and Machine Learning (XGBoost / Random Forest) predictive models. The estimated repair costs represent regional benchmark approximations and may vary based on authorized dealership quotations, OEM parts availability, and internal mechanical damages hidden beneath body panels.