VEHICLE DAMAGE ASSESSMENT REPORT

Certified Computer Vision & Deep Learning AI Estimate

VEHICLE DETAILS

Manufacturer: Hyundai
Model: Creta SX
Manufacturing Year: 2023
Registration Number: MH-12-AB-1234

INSPECTION SUMMARY

Images Analyzed: 4 (360° Multi-View)
Damaged Components: 6
Minor Damage: 1 | **Moderate:** 0 | **Severe:** 5
AI Fusion Status: Multi-angle duplicates consolidated

DAMAGED COMPONENTS & REPAIR BREAKDOWN

Vehicle Part	Damage Type	Severity	Area %	Action	Parts Cost	Labor	Total
Front Bumper	Dent	Severe	41.3%	Replace	■22,100	■7,080	■29,180
Headlight (Right)	Crack	Severe	41.5%	Replace	■27,920	■3,880	■31,800
Rear Bumper	Dent	Severe	28.5%	Replace	■19,650	■6,010	■25,660
Tail light (Right)	Crack	Severe	56.0%	Replace	■28,970	■4,240	■33,210
Front Door	Scratch	Minor	13.6%	Paint/Repair	■5,110	■2,320	■7,430
Front Door	Dent	Severe	32.1%	Replace	■33,070	■8,840	■41,910

Total Parts Cost:	**■136,820**	**ESTIMATED TOTAL REPAIR COST:**	**■169,190**
Total Labor Cost:	**■32,370**	**Estimated Range (95% CI):**	**■148,900 – ■192,900**

DISCLAIMER: This assessment is generated using Computer Vision (YOLOv8/11, Segmentation) and Machine Learning (XGBoost / Random Forest) predictive models. The estimated repair costs represent regional benchmark approximations and may vary based on authorized dealership quotations, OEM parts availability, and internal mechanical damages hidden beneath body panels.

Project developed for Bharath Institute of Higher Education and Research – 360° Auto Vision Platform.