| | site survey Checklist | | | |
|---|--|-------------------------|---|--|
| 1 | Required pictures Roof dimension including obstructions distance from ridges | Check/ uncheck Yes /No | Sample pictures | |
| 2 | Attic images with measurements (Rafter spacing) | Yes /No | | |
| 3 | Rafter dimesions (width) | Yes /No | | |
| 4 | Rafter dimesions (depth) | Yes /No | | |
| 5 | Attic cross section diagram with measurement | Yes /No | 2.54 TRUSS 24" OC 66" 2" EAVE | |
| 6 | Check for eave overhang (soffit) for rafter spacing in case of vaulted roof section or house plan document for measurement | Yes /No | | |
| 7 | Tilt angle from Attic using tilt tool mobile application | Yes /No | Place your mobile here. TO measure the root left. WE CAR SHAVE LIST BY ASSESSED BY INV. ALEXANDED THE DEVICE ASSESSED BY INV. | |
| 8 | Main breaker details with clear picture | Yes /No | 29 | |
| 9 | Customer main service panel clear picture & picture with | Yes /No | | |

| 10 | main service panel with deadfront open to identify any code violation | Yes /No | PANEL LOCATED INSIDE CLOTHES CLOSET |
|----|---|---------|--|
| 11 | service panel surrounding area picture to identify any code violation/Conductor run | Yes /No | CODE VIOLATION- |
| 12 | service panel surrounding area picture to identify any code violation/Conductor run | Yes /No | |
| 13 | Bus bar rating & electrical diagram clear picture | Yes /No | CAT. NO. 1416-14-200N THE ANALYSIS AND THE STREET OF THE S |
| 14 | Existing grounding rod for house | Yes /No | |
| 15 | Roof pictures from street view to identify roof obstructions | Yes /No | |
| 16 | Customer willing to cut trees | Yes /No | |