

ACN: 2372208

Time / Day

Date : 202606

Local Time Of Day : 0601-1200

Place

Locale Reference.Airport : BFI.Airport

State Reference : WA

Altitude.AGL.Single Value : 0

Aircraft : 1

Reference : X

ATC / Advisory.Ground : BFI

Aircraft Operator : Fractional

Make Model Name : Medium Transport, Low Wing, 2 Turbojet Eng

Crew Size.Number Of Crew : 2

Operating Under FAR Part : Part 91

Mission : Ferry / Re-Positioning

Flight Phase : Taxi

Aircraft : 2

Reference : Y

ATC / Advisory.Ground : BFI

Make Model Name : Medium Transport, Low Wing, 2 Turbojet Eng

Crew Size.Number Of Crew : 2

Flight Phase : Taxi

Person

Location Of Person.Aircraft : X

Location In Aircraft : Flight Deck

Reporter Organization : Fractional

Function.Flight Crew : Captain

Function.Flight Crew : Pilot Flying

Qualification.Flight Crew : Air Transport Pilot (ATP)

ASRS Report Number.Accession Number : 2372208

Human Factors : Communication Breakdown

Communication Breakdown.Party1 : Flight Crew

Communication Breakdown.Party2 : ATC

Events

Anomaly.ATC Issue : All Types

Anomaly.Conflict : Ground Conflict, Critical

Anomaly.Ground Excursion : Taxiway

Anomaly.No Specific Anomaly Occurred : Unwanted Situation

Detector.Person : Flight Crew

When Detected : Taxi

Result.Flight Crew : Requested ATC Assistance / Clarification

Assessments

Contributing Factors / Situations : Airport

Contributing Factors / Situations : Human Factors

Contributing Factors / Situations : Procedure

Primary Problem : Procedure

Narrative: 1

Cleared Runway 32L at A7 to A taxiway to the ramp. After taxiing about 400 feet ground instructed us to move right as far as possible to allow an aircraft to taxi southbound on right side of Taxiway A. We moved right with right wing well across non-movement line. Aircraft Y was taxiing south, it appeared our wing tips would be closer than 5 feet. I stopped my airplane, opposite traffic did also. Ground responded we do this everyday here as if to be proud of it.

Synopsis

Fractional Captain reported BFI Ground asked the crew during taxi to move over to the side of a taxiway to allow an opposite direction aircraft taxi past them, and stated BFI Ground often clears opposite direction aircraft in this manner posing a safety concern.